



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | JAGUAR |
| Model | X-TYPE SE |
| Colour | Black |
| Year of manufacture | - |
| Top speed | 125 mph |
| 0 - 60 mph | 9.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 130 BHP |
| Max. torque | 330 Nm at 1.800 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 50.4 mpg |




LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-31 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

| | |
|-------------------------|--|
| MOT #19 | 2022-09-12 10:32 |
| MOT test number | 250325844188 |
| Result | ✓ Passed |
| Next expiry date | 2023-09-11 |
| Advice | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| Advice | Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |

| | |
|------------------------|---|
| MOT #18 | 2022-09-07 12:33 |
| MOT test number | 149927062710 |
| Result | ✗ Failed |
| Advice | Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |
| Advice | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| Fail | Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b)) |

| | |
|------------------------|--|
| MOT #17 | 2021-09-09 11:42 |
| MOT test number | 787369044040 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Nearside Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |

**MOT #16**

2021-09-09 11:42

MOT test number

828358664141

Result

✗ Failed

Advice Nearside Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Offside Rear Parking brake inoperative on one side (1.4.1 (a))

Advice Offside Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15

2020-08-24 15:37

MOT test number

420171754788

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #14

2020-08-20 11:55

MOT test number

104986975858

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Fail Offside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Fail Nearside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #13

2019-08-22 14:44

MOT test number

139626269402

Result

✓ Passed

**MOT #12** 2018-08-07 10:19**MOT test number** 181071364784**Result** ✓ Passed**MOT #11** 2017-08-07 12:36**MOT test number** 359588849061**Result** ✓ Passed**MOT #10** 2017-08-07 12:36**MOT test number** 128368894164**Result** ✗ Failed

Pass with rectification Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Pass with rectification Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #9 2016-08-08 08:52**MOT test number** 424825767993**Result** ✓ Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)



MOT #8 2016-08-01 10:32

MOT test number 773602438860

Result ✗ Failed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Fail** Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #7 2015-08-05 14:54

MOT test number 977205609490

Result ✓ Passed

- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2015-08-05 14:11**MOT test number** 965707372754**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2014-08-04 11:40**MOT test number** 695436614226**Result** ✓ Passed**MOT #4** 2013-07-29 16:53**MOT test number** 636850313254**Result** ✓ Passed**MOT #3** 2013-07-29 11:18**MOT test number** 288620613235**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Nearside front tyre wearing on inner edge**MOT #2** 2012-08-07 10:25**MOT test number** 439040822251**Result** ✓ Passed



MOT #1 2011-08-09 15:46

MOT test number 808821721236

Result ✓ Passed

- Notice** All brake discs in a rusty condition
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | LV08GVZ |
| Plate since | 2019-03-29 |
| Current registration | LV08GVZ |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2008-03-10 |
| Last registration | 2022-09-12 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2008-03-10 | 22 mi |
| Registration #2 | 2011-08-09 | 30.399 mi |
| Registration #3 | 2012-08-07 | 40.520 mi |
| Registration #4 | 2013-07-29 | 43.722 mi |
| Registration #5 | 2013-07-29 | 43.722 mi |
| Registration #6 | 2014-08-04 | 46.017 mi |
| Registration #7 | 2015-08-05 | 48.505 mi |
| Registration #8 | 2015-08-05 | 48.518 mi |
| Registration #9 | 2016-08-01 | 52.069 mi |
| Registration #10 | 2016-08-08 | 52.070 mi |
| Registration #11 | 2017-08-07 | 56.707 mi |
| Registration #12 | 2018-08-07 | 61.344 mi |
| Registration #13 | 2019-08-07 | 65.981 mi |
| Registration #14 | 2020-08-07 | 70.618 mi |
| Registration #15 | 2021-08-07 | 75.255 mi |
| Registration #16 | 2022-08-07 | 79.892 mi |
| Registration #17 | 2023-08-07 | 84.529 mi |
| Registration #18 | 2024-08-07 | 89.166 mi |
| Registration #19 | 2025-08-07 | 93.803 mi |
| Registration #20 | 2026-08-07 | 98.440 mi |
| Registration #21 | 2027-08-07 | 103.077 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2003 mm |
| Height | 1395 mm |
| Length | 4672 mm |
| Wheel base | 2710 mm |
| Kerb weight | 1502 kg |
| Max. allowed weight | 2015 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 61 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 0806030302416G |