



report date: 2024-03-29

General information

Make	VOLVO
Model	S80 DRIVE R-DESIGN START/STOP
Colour	Black
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-07-30
Pictures	22
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-24
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	13
Total items failed	5

MOT #15	2023-08-04 13:06
MOT test number	150711840023
Result	✓ Passed
Next expiry date	2024-08-24
Advice	Nearside Rear Nail in tyre
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #14	2022-08-22 14:31
MOT test number	254531680422
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2021-08-25 13:10
MOT test number	499857163091
Result	✓ Passed

MOT #12	2021-04-13 16:07
MOT test number	616440631531
Result	✓ Passed

**MOT #11** 2021-04-06 16:25**MOT test number** 943287848676**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Exhaust mounting defective (6.1.2 (a))**MOT #10** 2020-12-21 14:27**MOT test number** 789976073974**Result** ✓ Passed**MOT #9** 2020-12-21 09:16**MOT test number** 319759059541**Result** ✗ Failed**Fail** Tyre tread depth below requirements of 1.6mm all 4 245/40/18 (5.2.3 (e))**MOT #8** 2019-06-18 15:49**MOT test number** 497188643837**Result** ✓ Passed**MOT #7** 2019-06-18 14:15**MOT test number** 202540248959**Result** ✗ Failed**Fail** Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #6** 2018-05-22 11:42**MOT test number** 222386845291**Result** ✓ Passed

Advice Offside Rear Suspension rod pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice Nearside Rear Suspension rod pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

MOT #5 2018-05-22 11:42**MOT test number** 755483998718**Result** ✗ Failed

Pass with rectification Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Advice Offside Rear Suspension rod pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice Nearside Rear Suspension rod pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

MOT #4 2017-05-22 11:56**MOT test number** 330484068598**Result** ✓ Passed**MOT #3** 2016-06-14 11:45**MOT test number** 908156637289**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2015-06-09 13:16**MOT test number** 697530165136**Result** ✓ Passed



MOT #1	2014-06-04 14:26
MOT test number	407935554190
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
24 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	24 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-06-21
Last registration	2023-08-04
Complete history	See info



Registration #1	2011-06-21	9 mi
Registration #2	2014-06-04	35.946 mi
Registration #3	2015-06-09	47.991 mi
Registration #4	2016-06-14	59.835 mi
Registration #5	2017-05-22	75.318 mi
Registration #6	2018-05-22	89.432 mi
Registration #7	2018-05-22	89.432 mi
Registration #8	2019-06-18	105.937 mi
Registration #9	2019-06-18	105.938 mi
Registration #10	2019-06-18	105.938 mi
Registration #11	2019-06-18	105.938 mi
Registration #12	2019-06-18	105.938 mi
Registration #13	2019-06-18	105.938 mi
Registration #14	2019-06-18	105.938 mi
Registration #15	2019-06-18	105.938 mi
Registration #16	2019-06-18	105.938 mi
Registration #17	2019-06-18	105.938 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1587 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4116932