



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Silver
Year of manufacture	2004
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.8 mpg
Consumption combined	40.3 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-30
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-24
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	31
Total items failed	24

MOT #23	2023-05-18 16:05
MOT test number	423881898236
Result	✓ Passed
Next expiry date	2024-05-24

MOT #22	2023-05-18 11:07
MOT test number	641882616756
Result	✗ Failed
<div><div>Fail</div>Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))</div>	
<div><div>Advice</div>Backbox heatshield insecure</div>	
<div><div>Advice</div>Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))</div>	

MOT #21	2022-05-11 14:31
MOT test number	699906324646
Result	✓ Passed

**MOT #20**

2022-05-11 09:37

MOT test number

387822836797

Result**✗ Failed**

- Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))
- Fail** Front Windscreen washer not working (3.5 (a))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #19

2021-05-25 11:24

MOT test number

262596989808

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on edges and close to legal limit (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge close to legal limit (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on edges and close to legal limit (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge close to legal limit (5.2.3 (e))

**MOT #18**

2021-05-24 10:20

MOT test number

770864024604

Result**✗ Failed**

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing on edges and close to legal limit (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge close to legal limit (5.2.3 (e))

Fail Exhaust has a major leak of exhaust gases center pipe (6.1.2 (a))

Fail Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge wearing on edges and close to legal limit (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge close to legal limit (5.2.3 (e))

Fail Emissions not tested (8.2.1.2 (d))

**MOT #17**

2021-04-09 11:57

MOT test number

156442417594

Result

✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Headlamp light intensity severely reduced (4.1.4 (a))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Front Windscreen washer not working (3.5 (a))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust has a major leak of exhaust gases centre silencer (6.1.2 (a))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #16

2020-01-24 16:19

MOT test number

550797019038

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15

2019-01-24 12:21

MOT test number

101373192197

Result

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #14** 2018-01-26 16:13**MOT test number** 744955718141**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #13** 2018-01-26 12:49**MOT test number** 710197844614**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #12** 2017-01-16 09:44**MOT test number** 850153469801**Result** ✓ Passed**MOT #11** 2016-01-19 16:30**MOT test number** 311739585796**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #10** 2015-02-02 10:08**MOT test number** 806243235096**Result** ✓ Passed

**MOT #9** 2014-01-27 13:01**MOT test number** 748207324072**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Notice** O/s/f tyre slight damage**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #8** 2013-01-16 11:12**MOT test number** 357246913020**Result** ✓ Passed**Notice** Bodywork damage**Notice** Under-trays fitted obscuring some underside components**Notice** Sill covers fitted**Notice** Osf tyre has slight damage to side wall**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #7** 2012-01-24 16:33**MOT test number** 199914322086**Result** ✓ Passed**MOT #6** 2011-01-21 15:42**MOT test number** 837351121003**Result** ✓ Passed**Notice** Slight brake binding osf

**MOT #5** 2011-01-12 15:24**MOT test number** 869862411043**Result** ✗ Failed**Notice** Slight brake binding osf**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #4** 2010-01-22 13:22**MOT test number** 761602020082**Result** ✓ Passed**MOT #3** 2009-01-16 12:42**MOT test number** 641716319019**Result** ✓ Passed**MOT #2** 2008-01-28 15:57**MOT test number** 850108428095**Result** ✓ Passed**Notice** Front pads 90% worn**MOT #1** 2007-01-12 10:36**MOT test number** 960742217066**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-01-24
Last registration	2023-05-18
Complete history	See info



Registration #1	2004-01-24	6 mi
Registration #2	2007-01-12	18.960 mi
Registration #3	2008-01-28	23.239 mi
Registration #4	2009-01-16	27.695 mi
Registration #5	2010-01-22	32.027 mi
Registration #6	2011-01-12	37.838 mi
Registration #7	2011-01-21	38.052 mi
Registration #8	2012-01-24	42.182 mi
Registration #9	2013-01-16	46.113 mi
Registration #10	2014-01-27	50.359 mi
Registration #11	2015-02-02	53.006 mi
Registration #12	2016-01-19	56.348 mi
Registration #13	2017-01-16	58.968 mi
Registration #14	2018-01-22	61.377 mi
Registration #15	2019-01-22	63.377 mi
Registration #16	2020-01-22	65.377 mi
Registration #17	2021-01-22	67.377 mi
Registration #18	2022-01-22	69.377 mi
Registration #19	2023-01-22	71.377 mi
Registration #20	2024-01-22	73.377 mi
Registration #21	2025-01-22	75.377 mi
Registration #22	2026-01-22	77.377 mi
Registration #23	2027-01-22	79.377 mi
Registration #24	2028-01-22	81.377 mi
Registration #25	2029-01-22	83.377 mi



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU520898