





report date: 2024-03-28

General information

Make	CITROEN
Model	DS5 HDI DSPORT
Colour	Silver
Year of manufacture	2013
Top speed	133 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history


Entry 1

Date 2021-10-10

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-08
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	41
Total items failed	15

MOT #12		2024-03-09 12:22	
MOT test i	umber	554283233966	
Result		✓ Passed	
Next expir	y date	2025-03-08	
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a)	(i))	
Advice (i))			
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice	Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice (a) (i))			
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/14



Advice

(a) (i))

KM63KSZ

report date: 2024-03-28

MOT #11 2024-03-08 10:10

MOT test number 858020846508

Result × Failed **Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) **Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) Fail **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt **Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt **Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/14

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4



report date: 2024-03-28

MOT #10

MOT test number

Result

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #9 2023-02-17 13:13 **MOT test number** 920020777116 Result **X** Failed Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail **Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #8	2022-01-11 12:03
MOT test number	816572612020
Result	✓ Passed
MOT #7	2020-12-03 11:23
MOT test number	956402127422
Result	✓ Passed

MOT #6	2019-11-28 16:52
MOT test number	565149830843
Result	✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #5 2018-11-28 14:43 923299269641 **MOT** test number Result ✓ Passed **Advice** Undertray fitted **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4

MOT test number

127822201045

Result

Advice Undertray fitted

MOT test number
906678708564

Result

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Advice Undertray fitted

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT test number
964460146615


Result

Advice
Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice
Offside Front tyre close to limit and smooth on inner edge

Advice
Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice
Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check





Tax status	Expired at 1 February 2023
Days left	452 days too late
MOT expiry date	8 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Plate since

KM63KSZ

report date: 2024-03-28

More info >

Owner history		
For how long did the current and previous owner(s) have this CITROEN? How many owners of have? Check it in the premium report and see all owner registrations. Download the full report		ROEN
HARMAN AND AND AND AND AND AND AND AND AND A		

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	OK ON THE STATE OF	
Plate since		

CarCheck.co.uk page 11/14



KM63KSZ report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-11-29
Last registration	2024-03-09
Complete history	See info



Registration #1	2013-11-29	26 mi
Registration #2	2016-11-26	53.978 mi
Registration #3	2016-11-26	53.978 mi
Registration #4	2017-11-28	65.870 mi
Registration #5	2017-12-04	65.870 mi
Registration #6	2018-11-28	75.452 mi
Registration #7	2019-11-28	87.934 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		71.777 es
Registration #12		11.777 es
Registration #13		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 13/14



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	89%
Children	83%
Pedestrian	40%
Safety systems	97%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1508 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1530 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYZE4093902

CarCheck.co.uk page 14/14