



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE HIGHLINE TDI (100BHP)
Colour	Silver
Year of manufacture	-
Top speed	119 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg






Internet history

Entry 4


Date	2022-01-05
Pictures	48
Listing price	View report



source: autotrader.co.uk

Entry 3

Date	2021-12-29
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2021-08-05
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-08-05
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history**

MOT #22	2023-04-14 09:28
MOT test number	470859424205
Result	✓ Passed
Next expiry date	2024-04-13
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Minor	Nearside Front Headlamp lens slightly defective lense discoloured BOTH SIDES (4.1.1 (b) (i))

MOT #21	2023-04-13 12:01
MOT test number	910176975537
Result	✗ Failed
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Minor	Nearside Front Headlamp lens slightly defective lense discoloured BOTH SIDES (4.1.1 (b) (i))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Offside Front Direction indicator incorrect colour (4.4.3 (a))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Fail	Nearside Front Direction indicator incorrect colour (4.4.3 (a))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #20**

2022-04-13 16:54

MOT test number

465481015543

Result

✓ Passed

- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))
- Advice** Rear exhaust box corroded
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

MOT #19

2022-04-13 15:30

MOT test number

287877758733

Result

✗ Failed

- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt both sides (2.1.3 (g) (ii))
- Fail** Nearside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))
- Advice** Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Minor** Front Outer Drive shaft joint constant velocity boot severely deteriorated both sides (6.1.7 (g) (i))

**MOT #18**

2020-10-01 13:02

MOT test number

529112641470

Result

✓ Passed

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17**

2020-09-23 11:07

MOT test number

949441377516

Result

✗ Failed

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Driver's airbag obviously inoperative (7.1.5 (c))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #16**

2019-09-23 13:08

MOT test number

157032798464

Result

✓ Passed

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #15** 2019-09-23 10:38**MOT test number** 370941048125**Result** ✗ Failed**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #14** 2018-09-28 12:29**MOT test number** 867630428435**Result** ✓ Passed**MOT #13** 2017-09-26 12:19**MOT test number** 885783421563**Result** ✓ Passed**MOT #12** 2016-11-19 10:35**MOT test number** 609709091920**Result** ✓ Passed**MOT #11** 2015-11-20 09:40**MOT test number** 969992689166**Result** ✓ Passed**MOT #10** 2015-11-20 09:40**MOT test number** 234416084750**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)

**MOT #9** 2014-11-04 10:04**MOT test number** 457398704465**Result** ✓ Passed**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #8** 2014-11-04 10:04**MOT test number** 416838104438**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Pass with rectification** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #7** 2013-10-30 13:46**MOT test number** 906163003343**Result** ✓ Passed**MOT #6** 2012-11-02 12:04**MOT test number** 295547302333**Result** ✓ Passed



MOT #5	2011-12-13 10:56
MOT test number	769877841300
Result	✓ Passed
MOT #4	2010-08-04 10:42
MOT test number	184296310213
Result	✓ Passed
MOT #3	2009-08-06 16:32
MOT test number	782848719251
Result	✓ Passed
MOT #2	2008-08-08 09:54
MOT test number	480141528234
Result	✓ Passed
MOT #1	2007-07-11 09:40
MOT test number	101192797159
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	VA04WSV
Plate since	2019-06-29
Current registration	VA04WSV
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-08-04
Last registration	2023-04-14
Complete history	See info



Registration #1	2004-08-04	13 mi
Registration #2	2007-07-11	32.137 mi
Registration #3	2008-08-08	43.058 mi
Registration #4	2009-08-06	52.419 mi
Registration #5	2010-08-04	59.254 mi
Registration #6	2011-12-13	67.673 mi
Registration #7	2012-11-02	74.374 mi
Registration #8	2013-10-30	79.872 mi
Registration #9	2014-11-04	82.760 mi
Registration #10	2015-11-20	90.934 mi
Registration #11	2015-11-20	90.934 mi
Registration #12	2016-11-19	100.051 mi
Registration #13	2017-09-26	103.851 mi
Registration #14	2018-05-22	103.851 mi
Registration #15	2018-05-22	103.851 mi
Registration #16	2018-05-22	103.851 mi
Registration #17	2018-05-22	103.851 mi
Registration #18	2018-05-22	103.851 mi
Registration #19	2018-05-22	103.851 mi
Registration #20	2018-05-22	103.851 mi
Registration #21	2018-05-22	103.851 mi
Registration #22	2018-05-22	103.851 mi
Registration #23	2018-05-22	103.851 mi
Registration #24	2018-05-22	103.851 mi
Registration #25	2018-05-22	103.851 mi
Registration #26	2018-05-22	103.851 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1462 mm
Length	4703 mm
Wheel base	2703 mm
Kerb weight	1566 kg
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	AVB 257261