



report date: 2024-03-28

General information

Make	KIA
Model	RIO 2
Colour	Silver
Year of manufacture	2010
Top speed	108 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





## MOT history

MOT expiry date	2024-03-17
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	38
Total items failed	11

MOT #15	2023-03-18 12:40
MOT test number	984830194260
Result	✓ Passed
Next expiry date	2024-03-17

MOT #14	2022-03-18 14:36
MOT test number	626113627242
Result	✓ Passed
Advice	Stop lamp(s) non-obligatory stop lamp not working high level (4.3.1 (a) (ii))

MOT #13	2022-03-18 11:51
MOT test number	938230878691
Result	✗ Failed
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
Advice	Stop lamp(s) non-obligatory stop lamp not working high level (4.3.1 (a) (ii))

MOT #12	2021-03-16 14:22
MOT test number	592946109636
Result	✓ Passed

**MOT #11**

2020-03-09 09:55

**MOT test number**

625405066486

**Result**

✓ Passed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear tyres slightly perished**MOT #10**

2020-03-04 17:32

**MOT test number**

199815658462

**Result**

✗ Failed

**Advice** Rear tyres slightly perished**Fail** Nearside Front Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #9**

2019-02-25 17:14

**MOT test number**

377804422999

**Result**

✓ Passed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8**

2019-02-22 12:41

**MOT test number**

186368540115

**Result****✗ Failed**

- Fail** Nearside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor** Offside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7**

2018-03-17 15:41

**MOT test number**

711156118113

**Result****✓ Passed**

**MOT #6** 2017-03-10 13:36**MOT test number** 104222422029**Result** ✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Front exhaust flexible section deteriorated
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Exhaust corroded

**MOT #5** 2017-03-10 10:20**MOT test number** 935055152717**Result** ✗ Failed

- Advice** Front exhaust mounting broken
- Advice** Front exhaust flexible section deteriorated
- Advice** Items removed from driver's view prior to test
- Advice** Centre exhaust mounting missing
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Exhaust corroded
- Fail** Offside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #4** 2016-02-20 13:26**MOT test number** 108669577881**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit 185/65/14 (4.1.E.1)
- Advice** Both rear tyres perished
- Advice** Nearside Rear Tyre worn close to the legal limit On legal limit (4.1.E.1)

**MOT #3** 2015-03-14 13:31**MOT test number** 738513875083**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-03-22 14:23**MOT test number** 115741584042**Result** ✓ Passed**Notice** Offside front tyre worn inner edge.**Notice** Centre exhaust mount broken, removed and placed in passenger footwell.**MOT #1** 2013-04-03 11:18**MOT test number** 279773793019**Result** ✓ Passed**Notice** Front wipers split at the ends but still clear the screen



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 March 2025

✗  
**MOT**  
  
Expired:  
17 March 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	17 March 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	GJ10ZZX
Plate since	2019-09-28
Current registration	GJ10ZZX
Plate since	2019-09-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-04-17
Last registration	2023-03-18
Complete history	<a href="#">See info</a>



Registration #1	2010-04-17	25 mi
Registration #2	2013-04-03	32.533 mi
Registration #3	2014-03-22	38.948 mi
Registration #4	2015-03-14	44.356 mi
Registration #5	2016-02-20	53.303 mi
Registration #6	2017-03-10	64.750 mi
Registration #7	2017-03-10	64.750 mi
Registration #8	2018-03-17	74.798 mi
Registration #9	2019-03-20	85.333 mi
Registration #10	2020-03-20	95.333 mi
Registration #11	2021-03-20	105.333 mi
Registration #12	2022-03-20	115.333 mi
Registration #13	2023-03-20	125.333 mi
Registration #14	2024-03-20	135.333 mi
Registration #15	2025-03-20	145.333 mi
Registration #16	2026-03-20	155.333 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1244 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4EEAH306877