





report date: 2024-03-29

## General information

Make	RENAULT
Model	CLIO DYNAMIQUE NAV
Colour	Blue
Year of manufacture	2018
Top speed	104 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	72 BHP
Max. torque	107 Nm at 4.250 rpm
Engine capacity	1.149 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/11



## Internet history

### Entry 2

Date	2021-08-05
D' I	

Pictures 1

Listing price <u>View report</u>



source: autotrader.co.uk

#### Entry 1

Date	2021-07-29
Pictures	8
Listing price	View report









source: cargurus.co.uk

CarCheck.co.uk page 2/11



## MOT history

MOT expiry date	2024-09-29
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	5

MOT #5		2023-09-19 09:33
MOT test	number	292693824843
Result		✓ Passed
Next expiry date 2024-09-		2024-09-29
Advice Offside Brake pipe corroded, covered in grease or other material Rear and Front (1.1.11 (c))		
Advice	Rear Service brake binding but not excessively both sides (1.2.1 (f))	

MOT #4	2022-09-28 13:3
MOT test	number 13629594456
Result	✓ Passe
Advice (c))	Front Brake pipe corroded, covered in grease or other material both sides feeding hoses (1.1.11
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



MOT #3 2022-09-28 09:14

**MOT test number** 986355305460

Result X Failed

**Pass with rectification** Nearside Headlamp aim too far to the right (4.1.2 (a))

Advice Front Brake pipe corroded, covered in grease or other material both sides feeding hoses (1.1.11 (c))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Nearside Rear Tyre has ply or cords exposed in tread (5.2.3 (d) (ii))

**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Fail** Nearside Front Tyre has ply or cords exposed in tread (5.2.3 (d) (ii))

MOT #2 2021-09-30 09:04

MOT test number 691435804682

**Result** ✓ Passed

MOT #1 2021-04-01 10:35

MOT test number 387536881531

Result \( \sqrt{Passed} \)

Advice Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	29 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
*******	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NIE SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-04-06
Last registration	2023-09-19
Complete history	See info



Registration #1	2018-04-06	13 mi
Registration #2	2021-04-01	18.772 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71,777 es

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



## Dimensions & weight

Width	1732 mm
Height	1448 mm
Length	4063 mm
Wheel base	2589 mm
Kerb weight	1059 kg
Max. allowed weight	1564 kg

# Additional information

Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

**Engine number** FC45511