





report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO HDI XTR
Colour	Grey
Year of manufacture	2012
Top speed	100 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	91 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-07-28
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	4
Total items failed	4

MOT #11	2023-07-17 14:50
MOT test number	267510708820
Result	✓ Passed
Next expiry date	2024-07-28

MOT #10	2022-07-20 07:15
MOT test number	257908000344
Result	✓ Passed

MOT #9	2022-07-18 10:28
MOT test number	961600697334
Result	× Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt clip (6.1.7 (g) (ii))

MOT #8	2021-07-29 08:04
MOT test number	208121486370
Result	✓ Passed
MOT #7	2019-05-21 14:24
MOT test number	203181633104
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #6 2018-06-01 09:36

MOT test number 573998258448

Result \rightarrow Passed

MOT #5 2017-06-15 08:14

MOT test number 811993493021

Result ✓ Passed

MOT #4 2016-08-02 13:02

MOT test number 529544056446

Result \(\sqrt{Passed} \)

Advice 2x exhaust centre box mounts breaking up

MOT #3 2015-09-02 14:18

MOT test number 192233623447

Result \rightarrow Passed

MOT #2 2015-09-02 10:13

MOT test number 705250957073

Result X Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1 2014-10-27 11:44

MOT test number 509360604300

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	28 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full respectively.	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NK AND
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-01-13
Last registration	2023-07-17
Complete history	See info



Registration #1	2012-01-13	14 mi
Registration #2	2014-10-27	16.287 mi
Registration #3	2015-09-02	20.575 mi
Registration #4	2015-09-02	20.578 mi
Registration #5	2016-08-02	25.739 mi
Registration #6	2017-06-15	30.980 mi
Registration #7	2018-06-01	31.872 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		10.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1862 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1410 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBEE0034993

CarCheck.co.uk page 11/11