



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	CAPTUR DYNAMIQUE MEDIANAV ENERGY TCE S/S
Colour	Black
Year of manufacture	2013
Top speed	106 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	898 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-03
Pictures	0
Listing price	<a href="#">View report</a>

source: autoonline.co.uk



MOT history

MOT expiry date	2024-10-12
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	7
Total items failed	12

MOT #9	2023-10-03 08:44
MOT test number	348560190219
Result	✓ Passed
Next expiry date	2024-10-12
Advice	O/s/r spring not sat in place + slight corrosion on under body

MOT #8	2022-10-13 09:15
MOT test number	403880146660
Result	✓ Passed

MOT #7	2021-08-20 16:17
MOT test number	434875888322
Result	✓ Passed

**MOT #6**

2021-03-25 17:40

**MOT test number**

134856572300

**Result**

✗ Failed

- Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Front Suspension arm damaged but not seriously weakened Wishbone (5.3.3 (b) (i))
- Advice** Brake pad(s) wearing thin Both sets of fronts (1.1.13 (a) (ii))
- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Suspension arm ball joint excessively worn Bottom ball joint (5.3.4 (a) (i))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Offside Front Daytime running light inoperative
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

**MOT #5**

2019-11-18 17:37

**MOT test number**

257835300506

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2018-11-02 16:06**MOT test number** 819039243708**Result** ✓ Passed**Advice** Imbalance to rear service brakes lower effort to offside**MOT #3** 2017-10-17 07:51**MOT test number** 758529110116**Result** ✓ Passed**MOT #2** 2017-10-13 13:16**MOT test number** 688589433064**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2017-01-26 12:11**MOT test number** 197509525704**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-06-21
Last registration	2023-10-03
Complete history	<a href="#">See info</a>



Registration #1	2013-06-21	16 mi
Registration #2	2017-01-26	40.136 mi
Registration #3	2017-10-13	45.990 mi
Registration #4	2017-10-17	45.990 mi
Registration #5	2018-11-02	48.170 mi
Registration #6	2019-11-18	58.451 mi
Registration #7	2020-05-20	59.277 mi
Registration #8	2020-05-20	59.277 mi
Registration #9	2020-05-20	59.277 mi
Registration #10	2020-05-20	59.277 mi
Registration #11	2023-10-03	59.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	79%
Pedestrian	61%
Safety systems	81%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1778 mm
Height	1566 mm
Length	4122 mm
Wheel base	2606 mm
Kerb weight	1089 kg
Max. allowed weight	1663 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D021489