





report date: 2024-03-29

### General information

Make	FORD
Model	TOURNEO CONNECT GRAND ZETEC TDCI
Colour	White
Year of manufacture	2015
Top speed	103 mph
0 - 60 mph	14.1 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	58.9 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/13




# Internet history

### Entry 1

Date 2021-12-23

Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-25
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	19
Total items failed	11


MOT #11		2024-01-26 15:06
MOT test	number	896516834954
Result		✓ Passed
Next expi	ry date	2025-01-25
Advice	Oil leak, but not excessive (engine area) recommend attention (8.4.1 (a)	(i))
Advice Offside Rear Seat belt webbing slightly damaged or frayed slightly frayed (7.1.2 (b) (ii))		
Advice	Front Play in steering rack inner joint(s) both sides	
Advice	Rear Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))	

CarCheck.co.uk page 3/13



CX15AYT

report date: 2024-03-29



MOT #9		2023-01-24 12:45
MOT test	number	984742252384
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both sides worn on edges (5.2.3	(e))
Advice	Oil leak, but not excessive engine area (8.4.1 (a) (i))	
Advice	Offside Front Play in steering rack inner joint(s)	

CarCheck.co.uk page 4/13



CX15AYT

report date: 2024-03-29

MOT #8 2023-01-18 14:49

**MOT test number** 397857433133

**Result** X Failed

Fail Offside Rear Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))

Fail Offside Rear Bumper likely to become detached (6.1.4 (a) (ii))

Fail Rear Seat belt buckle missing centre (7.1.2 (d))

**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #7 2022-01-20 17:53

**MOT test number** 461727279764

MOT #6 2021-04-22 10:56

**MOT test number** 988214184775

Result 

Passed

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Passenger seat(s) missing at time of test

**MOT #5** 2021-04-14 14:38

**MOT test number** 622575179002

**Result** X Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Passenger seat(s) missing at time of test

**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

CarCheck.co.uk page 5/13



MOT #4 2020-06-11 10:14

**MOT test number** 722016882167

MOT #3 2020-06-11 10:14

**MOT test number** 824493556334

Result × Failed

**Pass with rectification** Brake pedal anti-slip provision missing (1.1.2 (c))

**MOT #2** 2019-06-24 15:37

**MOT test number** 158062464062

**Result** ✓ Passed

MOT #1 2018-06-26 10:44

**MOT test number** 573400492626

**Result** 
✓ Passed

Advice Front Tyre worn close to legal limit/worn on edge worn on inside (5.2.3 (e))

Advice Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

CarCheck.co.uk page 6/13



### Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	25 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

*		
For how long did the current and previous owner(s) have this FORD? How many owners defect it in the premium report and see all owner registrations. Download the full report is		ave?
********		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-08-01
Last registration	2024-01-26
Complete history	See info



Registration #1	2015-08-01	24 mi
Registration #2	2018-06-26	58.298 mi
Registration #3	2019-06-24	73.116 mi
Registration #4	2020-06-11	89.913 mi
Registration #5	2020-06-11	89.913 mi
Registration #6	2021-04-14	106.570 mi
Registration #7	2021-04-22	106.572 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 ms
Registration #12		11.777 es
Registration #13		11.777 mi

More info >

CarCheck.co.uk page 12/13



### Car features

50225	Air conditionir
50295	
50482	
60501	
60566	
0567	
60569	

## Safety ratings

NCAP rating	****
Adult	94%
Children	85%
Pedestrian	62%
Safety systems	70%
Overall rating	83%
Video	see crash video



## Dimensions & weight

Width	1835 mm
Height	1861 mm
Length	4818 mm
Kerb weight	1517 kg
Max. allowed weight	2315 kg

## Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number Carcheck.co.uk	EA20848 page 13/13