



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI STYLE BLUE DRIVE
Colour	Silver
Year of manufacture	2014
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 2


Date	2021-07-31
Pictures	22
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-18
Pictures	24
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-03
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #10	2024-02-15 13:56
MOT test number	236961570920
Result	✓ Passed
Next expiry date	2025-03-03
Advice	Offside Front Tyre worn close to legal limit/worn on edge bald outer edges (5.2.3 (e))

MOT #9	2023-03-01 15:06
MOT test number	286771174739
Result	✓ Passed

MOT #8	2022-02-21 12:16
MOT test number	380321323748
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #7	2022-02-21 12:16
MOT test number	975739507536
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2021-02-27 11:37**MOT test number** 861443835219**Result** ✓ Passed**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Wiper blade split**MOT #5** 2021-02-26 12:56**MOT test number** 464160300479**Result** ✗ Failed**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Rear Registration plate does not conform to the specified requirements Delaminated (0.1 (d))**Advice** Rear Wiper blade split**MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MAJOR** Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #4** 2020-02-10 10:10**MOT test number** 559457214211**Result** ✓ Passed

**MOT #3** 2019-02-25 09:54**MOT test number** 459478851267**Result** ✓ Passed**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2018-02-23 11:54**MOT test number** 836413980598**Result** ✓ Passed**Advice** Under trays fitted unable to inspect some areas of suspension/steering/brakes /vehicle structure**MOT #1** 2017-02-27 10:34**MOT test number** 368222475201**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
3 March 2025

Tax status	Valid until 1 August
Days left	95
MOT expiry date	3 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EX14LVU
Plate since	2019-09-29
Current registration	EX14LVU
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-04
Last registration	2024-02-15
Complete history	See info



Registration #1	2014-03-04	6 mi
Registration #2	2017-02-27	35.270 mi
Registration #3	2018-02-23	45.104 mi
Registration #4	2019-02-25	54.189 mi
Registration #5	2020-02-10	63.134 mi
Registration #6	2021-02-26	69.821 mi
Registration #7	2021-02-27	69.822 mi
Registration #8	2022-02-28	75.277 mi
Registration #9	2023-02-28	80.277 mi
Registration #10	2023-02-28	85.277 mi
Registration #11	2023-02-28	90.277 mi
Registration #12	2023-02-28	95.277 mi
Registration #13	2024-02-15	100.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1648 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDEU412572