



PEUGEOT



VK56ZSJ


report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 ALLURE COUPE CABRIOLET
Colour	Silver
Year of manufacture	2006
Top speed	120 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.4 mpg
CO2 emission	166 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-01
Pictures	24
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-07-13
<b>MOT pass rate</b>	61 %
<b>MOT passed</b>	14
<b>Failed MOT tests</b>	9
<b>Total advice items</b>	56
<b>Total items failed</b>	15

**MOT #23** 2023-07-07 10:40**MOT test number** 609137054544**Result** Passed**Next expiry date** 2024-07-13

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 205/45R16 87w xl (5.2.3 (d) (ii))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #22** 2022-07-14 15:54**MOT test number** 751294215048**Result** Passed

- Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #21**

2022-07-14 11:53

**MOT test number**

328325310296

**Result****✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #20**

2021-06-29 12:43

**MOT test number**

670103485952

**Result****✓ Passed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened surface corrosion (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner faces (1.1.14 (a) (ii))**MOT #19**

2020-11-24 16:15

**MOT test number**

945531384736

**Result****✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing sidewall cracked + damaged (5.2.3 (d) (ii))**Advice** Fuel tank securing strap corroded**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre slightly damaged sidewall (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner surfaces (1.1.14 (a) (ii))

**MOT #18** 2020-11-11 17:35**MOT test number** 847069310903**Result** ✗ Failed**Fail** Rear Rear fog lamp switch inoperative wont switch off (4.5.3 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #17** 2019-03-28 17:11**MOT test number** 655013967806**Result** ✓ Passed**Advice** Brake disc worn, but not excessively inner surfaces (1.1.14 (a) (i))**MOT #16** 2019-03-28 17:11**MOT test number** 626756621159**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Brake disc worn, but not excessively inner surfaces (1.1.14 (a) (i))**MOT #15** 2018-04-06 09:19**MOT test number** 361443871652**Result** ✓ Passed**MOT #14** 2018-04-05 16:27**MOT test number** 667207850537**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #13** 2017-06-12 10:13**MOT test number** 417193358812**Result** ✓ Passed**MOT #12** 2017-06-12 10:13**MOT test number** 863653373404**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #11** 2016-07-01 13:59**MOT test number** 315262376801**Result** ✓ Passed**MOT #10** 2015-08-24 00:00**MOT test number** 225571011770**Result** ✗ Failed**Fail** Front front parking (secondary) brakes imbalanced (3.7.B.6b)**Fail** Steering column shaft has excessive end float both front steering rack ends (2.1.3)**MOT #9** 2014-12-23 12:28**MOT test number** 477317154391**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**Notice** O/s/r tyre wearing uneven on inner edge**Notice** Slight flat spot n/s/f tyre**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)**Notice** N/s/f fog lamp damaged

**MOT #8**

2014-12-22 11:04

**MOT test number**

216056854313

**Result****✗ Failed**

- Notice** N/s/f fog lamp damaged
- Notice** Play in steering rack inner joint(s)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)
- Notice** O/s/r tyre wearing uneven on inner edge
- Notice** Slight flat spot n/s/f tyre
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #7**

2013-11-08 14:52

**MOT test number**

867162313351

**Result****✓ Passed**

- Notice** Outer casing of rear silencer corroded
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** N/s/f wheel rim damaged
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Ball joint has slight play (2.2.B.1f)

**MOT #6**

2013-11-08 10:46

**MOT test number**

646552213332

**Result****✗ Failed****Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Ball joint has slight play (2.2.B.1f)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** N/s/f wheel rim damaged**Notice** Outer casing of rear silencer corroded**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5**

2012-11-06 10:06

**MOT test number**

738471612320

**Result****✓ Passed****Notice** Outer casing of rear silencer corroded**Notice** Slight play o/s track rod inner ball joint**Notice** Front brake discs slightly worn and pitted**Notice** Slight play n/s track rod inner ball joint



**MOT #4** 2012-11-06 10:06**MOT test number** 836701212398**Result** ✗ Failed**Notice** Slight play o/s track rod inner ball joint**Pass with rectification** Offside Headlamp aim too high (1.8)**Notice** Front brake discs slightly worn and pitted**Notice** Slight play n/s track rod inner ball joint**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Outer casing of rear silencer corroded**MOT #3** 2011-10-24 09:38**MOT test number** 577457791288**Result** ✓ Passed**MOT #2** 2010-10-23 13:54**MOT test number** 240166190276**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-10-24 15:44**MOT test number** 350457799470**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
13 July 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	13 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>VK56ZSJ</b>
Plate since	2024-03-29
Current registration	<b>VK56ZSJ</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-10-31
Last registration	2023-07-07
Complete history	<a href="#">See info</a>



Registration #1	2006-10-31	11 mi
Registration #2	2009-10-24	28.613 mi
Registration #3	2010-10-23	31.798 mi
Registration #4	2011-10-24	37.925 mi
Registration #5	2012-11-06	43.275 mi
Registration #6	2013-11-08	51.744 mi
Registration #7	2013-11-08	51.744 mi
Registration #8	2014-12-22	57.749 mi
Registration #9	2014-12-23	57.749 mi
Registration #10	2015-08-24	57.889 mi
Registration #11	2016-07-01	57.920 mi
Registration #12	2017-06-12	61.500 mi
Registration #13	2018-06-20	65.277 mi
Registration #14	2018-06-20	65.277 mi
Registration #15	2018-06-20	65.277 mi
Registration #16	2018-06-20	65.277 mi
Registration #17	2018-06-20	65.277 mi
Registration #18	2018-06-20	65.277 mi
Registration #19	2018-06-20	65.277 mi
Registration #20	2018-06-20	65.277 mi
Registration #21	2018-06-20	65.277 mi
Registration #22	2018-06-20	65.277 mi
Registration #23	2018-06-20	65.277 mi
Registration #24	2018-06-20	65.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1893 mm
Height	1373 mm
Length	3835 mm
Wheel base	2442 mm
Kerb weight	1215 kg
Max. allowed weight	1535 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4



<b>Number of axles</b>	2
<b>Engine number</b>	FX6N3094473