



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC I-MUSIC DCI
Colour	Black
Year of manufacture	2010
Top speed	111 mph
0 - 100 km/h	12.4 seconds
0 - 60 mph	11.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	78 kW / 106 HP / 105 BHP
Max. torque	240 Nm at 2.000 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-08-05
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-09
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	19
Total items failed	9

MOT #16	2023-08-10 15:55
MOT test number	277708493687
Result	✓ Passed
Next expiry date	2024-08-09
Advice	Nearside Play in steering rack inner joint(s)
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #15	2023-08-10 07:50
MOT test number	716351447734
Result	✗ Failed
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Fail	Rear fog lamp tell-tale not working (4.9.1 (a) (ii))
Advice	Nearside Play in steering rack inner joint(s)
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #14** 2022-08-22 07:41**MOT test number** 705886884927**Result** ✓ Passed**MOT #13** 2021-09-21 14:28**MOT test number** 186038283533**Result** ✓ Passed**MOT #12** 2021-02-19 14:50**MOT test number** 614448658831**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11** 2021-02-19 11:04**MOT test number** 211372058368**Result** ✗ Failed

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2020-03-09 08:47**MOT test number** 247789871502**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #9** 2019-03-11 15:27**MOT test number** 708381975789**Result** ✓ Passed**MOT #8** 2019-03-11 09:39**MOT test number** 645256107316**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #7** 2018-02-26 10:12**MOT test number** 261609832092**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2017-03-08 15:26**MOT test number** 121126869961**Result** ✓ Passed

**MOT #5** 2017-03-08 09:47**MOT test number** 743416830314**Result** ✗ Failed

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall (4.1.D.1a)

**MOT #4** 2016-03-10 13:26**MOT test number** 702664594746**Result** ✓ Passed

**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #3** 2015-03-04 15:15**MOT test number** 379983765061**Result** ✓ Passed

**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #2** 2014-03-12 14:29**MOT test number** 139121174043**Result** ✓ Passed**MOT #1** 2013-11-28 11:44**MOT test number** 965782833371**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
9 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	9 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-11-29
Last registration	2023-08-10
Complete history	<a href="#">See info</a>



Registration #1	2010-11-29	6 mi
Registration #2	2013-11-28	30.634 mi
Registration #3	2014-03-12	32.649 mi
Registration #4	2015-03-04	41.893 mi
Registration #5	2016-03-10	49.986 mi
Registration #6	2017-03-08	58.253 mi
Registration #7	2017-03-08	58.253 mi
Registration #8	2018-02-26	65.027 mi
Registration #9	2019-03-11	72.991 mi
Registration #10	2020-03-10	80.955 mi
Registration #11	2021-03-10	88.919 mi
Registration #12	2022-03-10	96.883 mi
Registration #13	2023-03-10	104.847 mi
Registration #14	2024-03-10	112.811 mi
Registration #15	2025-03-10	120.775 mi
Registration #16	2026-03-10	128.739 mi
Registration #17	2027-03-10	136.703 mi
Registration #18	2028-03-10	144.667 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	49 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D216709