






report date: 2024-03-28

General information

Make	FORD
Model	S-MAX GHIA TDCI
Colour	Silver
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28

B 4	\sim $-$			
10.71	α	- h	sto	rv
101	() I		510	II V
	•			. ,

MOT expiry date	2025-04-21
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	18
Total items failed	14

MOT #15	2024-04-15 07:28
MOT test number	934032891306
Result	✓ Passed
Next expiry date	2025-04-21

MOT #14	2023-04-18 08:42
MOT test number	831203967555
Result	✓ Passed

MOT #13	2022-04-22 17:57
MOT test number	491106380862
Result	✓ Passed

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT #12 2022-03-10 16:15

MOT test number 226018933035

Result X Failed

Fail Nearside Rear Suspension arm pin or bush excessively worn forward arm bush (5.3.4 (a) (i))

Fail Central Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail Nearside Headlamp aim too high (4.1.2 (a))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Towbar attachment insecure (6.1.6 (c) (i))

Advice Unable to test towbar 13pin socket

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Minor Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Fail Emissions not tested exhaust leak (8.2.2.2 (e))

Fail Offside Headlamp aim too high (4.1.2 (a))

MOT #11 2021-02-23 14:50

MOT test number 500776418512

Result

Passed

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #10 2021-02-22 17:04 623910203189 **MOT** test number Result × Failed Fail Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail **Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #9

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #8 2019-01-24 16:20

MOT test number 447938352122

Result ✓ Passed

MOT test number

783210204924

Result

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Advice Central brake light n/w

Fail Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

CarCheck.co.uk page 4/13



SG59XYE

report date: 2024-03-28

MOT #6		2018-01-22 09:29
MOT test	number	697341603313
Result		✓ Passed
MOT #5		2016-12-05 17:08
MOT test	number	840062847573
Result		✓ Passed
MOT #4		2015-12-12 09:06
MOT test	number	882650841125
Result		✓ Passed
Advice	Child seat fitted to offside rear seat unable to fully inspect adult belt	
Advice	Direction indicator slightly discoloured both rear (1.4.A.2f)	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Tow bar ball not fitted at time of test	
Advice	Furthest rear seats folded away an cover by a load liner seat belts not inspected	I
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #3		2014-12-23 12:35
MOT test	number	647227354383
Result		✓ Passed
Notice	Nail in nearside rear tyre	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	
Notice	Message on dash bonnet open but is closed	

CarCheck.co.uk page 5/13



SG59XYE report date: 2024-03-28

MOT #2	2013-09-24 10:04
MOT test number	627847163286
Result	✓ Passed
MOT #1	2012-09-26 15:50
MOT test number	709590772277
Result	✓ Passed

CarCheck.co.uk page 6/13



SG59XYE report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	21 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13




report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner	hictory
UWILEI	HISTOLV

,		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ave?

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	NK NK	
Plate since		
Current registration	NK SIN	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-25
Last registration	2024-04-15
Complete history	See info



Registration #1	2009-09-25	27 mi
Registration #2	2012-09-26	26.923 mi
Registration #3	2013-09-24	33.242 mi
Registration #4	2014-12-23	45.330 mi
Registration #5	2015-12-12	56.426 mi
Registration #6	2016-12-05	63.405 mi
Registration #7	2018-01-22	71.102 mi
Registration #8	2019-01-23	87.253 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



SG59XYE report date: 2024-03-28

Car features

50225	Air conditionir
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1

Number of axles 2

Engine number 9K79192