



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO VVTI T3
Colour	Blue
Year of manufacture	2005
Top speed	121 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 2


Date	2021-07-28
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-26
Pictures	37
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-31
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	19
Total items failed	8

MOT #22	2023-07-22 14:20
MOT test number	456202939013
Result	✓ Passed
Next expiry date	2024-07-31
Advice	Parking break lever taviling slightly high

MOT #21	2023-07-22 11:23
MOT test number	170611500702
Result	✗ Failed
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Parking break lever taviling slightly high
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #20	2022-08-01 11:10
MOT test number	143880109442
Result	✓ Passed

**MOT #19** 2022-08-01 11:10**MOT test number** 402435541431**Result** ✗ Failed

Pass with rectification Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #18 2021-07-28 16:09**MOT test number** 733615290145**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, but not excessively offside and nearside (1.1.14 (a) (i))

MOT #17 2020-12-15 16:31**MOT test number** 520604416736**Result** ✓ Passed

Advice Rear Brake disc worn, but not excessively offside and rear side (1.1.14 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake disc worn, but not excessively offside and nearside (1.1.14 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16 2020-03-20 15:06**MOT test number** 610624486407**Result** ✓ Passed

**MOT #15** 2019-03-16 08:45**MOT test number** 982715239154**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2018-03-17 08:50**MOT test number** 298579612267**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #13** 2017-03-19 11:28**MOT test number** 475250945078**Result** ✓ Passed**Advice** Nearside Front tyre wearing on inner and outer edges**MOT #12** 2016-03-15 10:08**MOT test number** 724940849966**Result** ✓ Passed**Advice** Nearside Front Tyre wearing on inner and outer edge**MOT #11** 2015-03-07 10:08**MOT test number** 939146065054**Result** ✓ Passed**Notice** Nail in rear tyre**Notice** O/s/r tyre wearing on inner edges**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #10** 2014-03-11 09:53**MOT test number** 185960474479**Result** ✓ Passed**MOT #9** 2014-03-11 09:53**MOT test number** 325800474085**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #8** 2013-03-11 17:12**MOT test number** 837590673097**Result** ✓ Passed**MOT #7** 2012-03-19 10:22**MOT test number** 557069472034**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2012-03-19 10:22**MOT test number** 548289172031**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2011-03-19 10:09**MOT test number** 757898671051**Result** ✓ Passed**Notice** O/s/r tyre wall cracked



MOT #4	2010-03-19 16:57
MOT test number	630298470096
Result	✓ Passed
MOT #3	2010-03-19 14:09
MOT test number	491698570083
Result	✗ Failed
<div><div>Fail</div>Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)</div>	
MOT #2	2009-03-13 11:44
MOT test number	444802979089
Result	✓ Passed
MOT #1	2008-04-28 16:02
MOT test number	913459218190
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
31 July 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-05-24
Last registration	2023-07-22
Complete history	See info



Registration #1	2005-05-24	14 mi
Registration #2	2008-04-28	8.769 mi
Registration #3	2009-03-13	15.415 mi
Registration #4	2010-03-19	23.314 mi
Registration #5	2010-03-19	23.227 mi
Registration #6	2011-03-19	29.861 mi
Registration #7	2012-03-19	35.116 mi
Registration #8	2013-03-11	41.751 mi
Registration #9	2014-03-11	47.397 mi
Registration #10	2015-03-07	52.515 mi
Registration #11	2016-03-15	59.424 mi
Registration #12	2017-03-19	62.407 mi
Registration #13	2018-03-19	65.390 mi
Registration #14	2019-03-19	68.373 mi
Registration #15	2020-03-19	71.356 mi
Registration #16	2021-03-19	74.339 mi
Registration #17	2022-03-19	77.322 mi
Registration #18	2023-03-19	80.305 mi
Registration #19	2024-03-19	83.288 mi
Registration #20	2025-03-19	86.271 mi
Registration #21	2026-03-19	89.254 mi
Registration #22	2027-03-19	92.237 mi
Registration #23	2028-03-19	95.220 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1ZZE204138