



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA VVTi
Colour	Black
Year of manufacture	2003
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	172 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-05
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2018-10-10
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	16
Total items failed	20

MOT #172018-10-11 11:22

MOT test number177747302372

Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Offside Headlamp light intensity severely reduced (4.1.4 (a))
Fail	Exhaust emits clearly visible black smoke during acceleration (8.2.1.2 (g))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Nearside Headlamp light intensity severely reduced (4.1.4 (a))
Fail	Exhaust emits clearly visible black smoke during acceleration (8.2.1.2 (g))

MOT #162017-10-07 10:17

MOT test number294404211465

Result	✓ Passed
Advice	Exhaust emits blue smoke during acceleration (7.3.A.2c)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #15**

2017-10-02 10:32

**MOT test number**

235749931513

**Result**

✗ Failed

**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Rear Exhaust has a major leak of exhaust gases box (7.1.2)**Advice** Exhaust emits blue smoke during acceleration (7.3.A.2c)**MOT #14**

2016-10-08 09:40

**MOT test number**

459370085418

**Result**

✓ Passed

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Rear Exhaust has a minor leak of exhaust gases box (7.1.2)**MOT #13**

2015-10-02 09:44

**MOT test number**

869469418027

**Result**

✓ Passed

**MOT #12**

2014-09-30 16:19

**MOT test number**

139893474282

**Result**

✓ Passed

**Notice** Front screen has slight scoring

**MOT #11** 2014-09-30 11:19**MOT test number** 367963774402**Result** ✗ Failed**Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)**Notice** Front screen has slight scoring**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2013-10-01 14:55**MOT test number** 397174373468**Result** ✓ Passed**MOT #9** 2013-10-01 11:34**MOT test number** 626514173243**Result** ✗ Failed**Fail** Offside Front Brakes imbalanced across an axle (3.7.B.5b)**Notice** Both rear tyres showing cracks across tread and slightly out of shape.**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Brakes imbalanced across an axle (3.7.B.5b)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2012-09-26 11:06**MOT test number** 728390572258**Result** ✓ Passed

**MOT #7** 2011-09-20 14:24**MOT test number** 139063461249**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2010-09-21 09:14**MOT test number** 393664460292**Result** ✓ Passed**MOT #5** 2009-09-18 09:22**MOT test number** 353041569499**Result** ✓ Passed**MOT #4** 2008-09-27 09:25**MOT test number** 392431778242**Result** ✓ Passed**MOT #3** 2007-09-26 16:46**MOT test number** 761369367264**Result** ✓ Passed

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #2** 2006-10-11 15:09**MOT test number** 290844086294**Result** ✓ Passed



MOT #1	2006-04-03 15:53
MOT test number	150623096433
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
30 November 2018

✕  
MOT

Expired:  
10 October 2018

Tax status	Expired at 30 November 2018
Days left	1976 days too late
MOT expiry date	10 October 2018
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2003-03-31
Last registration	2018-10-11
Complete history	<a href="#">See info</a>



Registration #1	2003-03-31	22 mi
Registration #2	2006-04-03	30.060 mi
Registration #3	2006-10-11	36.421 mi
Registration #4	2007-09-26	40.670 mi
Registration #5	2008-09-27	44.880 mi
Registration #6	2009-09-18	48.514 mi
Registration #7	2010-09-21	53.302 mi
Registration #8	2011-09-20	58.185 mi
Registration #9	2012-09-26	63.042 mi
Registration #10	2013-10-01	67.719 mi
Registration #11	2014-10-01	72.396 mi
Registration #12	2015-10-01	77.073 mi
Registration #13	2016-10-01	81.750 mi
Registration #14	2017-10-01	86.427 mi
Registration #15	2018-10-01	91.104 mi
Registration #16	2019-10-01	95.781 mi
Registration #17	2020-10-01	100.458 mi
Registration #18	2021-10-01	105.135 mi
Registration #19	2022-10-01	109.812 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	1ZZ1324678