



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA DESIGN CDTI 16V
Colour	Black
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	150 BHP
Max. torque	315 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	186 g/km
CO2 label	J





Internet history

Entry 2

Date	2022-06-03
Pictures	36
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-22
Pictures	0
Listing price	View report

source: yesauto.com



MOT history

MOT expiry date	2024-11-28
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	22
Total items failed	4

MOT #19	2023-11-29 10:26
MOT test number	926144242136
Result	✓ Passed
Next expiry date	2024-11-28
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #18	2023-11-28 16:49
MOT test number	410361514777
Result	✗ Failed
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
DANGEROUS	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17** 2022-11-21 16:44**MOT test number** 151601813154**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #16** 2021-11-29 10:14**MOT test number** 724327550887**Result** ✓ Passed**Advice** Stonechip in swept area of windscreen**MOT #15** 2021-11-26 16:27**MOT test number** 908257371606**Result** ✗ Failed**MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Stonechip in swept area of windscreen**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #14** 2021-03-04 10:55**MOT test number** 974810465769**Result** ✓ Passed**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Engine malfunction light on**MOT #13** 2020-02-28 15:38**MOT test number** 263224660074**Result** ✓ Passed



MOT #12 2020-02-28 12:05

MOT test number 271148904004

Result ✗ Failed

MAJOR Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #11 2019-03-01 10:05

MOT test number 285222216947

Result ✓ Passed

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10 2018-03-09 08:38

MOT test number 391876150930

Result ✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #9 2018-03-09 08:38

MOT test number 998150201960

Result ✗ Failed

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Pass with rectification Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #8 2017-03-18 09:24

MOT test number 809148198257

Result ✓ Passed



MOT #7	2016-04-05 08:05
MOT test number	595060451605
Result	✓ Passed
MOT #6	2015-04-04 09:27
MOT test number	438134595002
Result	✓ Passed
MOT #5	2014-03-29 11:54
MOT test number	659408084026
Result	✓ Passed
MOT #4	2013-04-06 09:44
MOT test number	105866393427
Result	✓ Passed
MOT #3	2012-04-18 13:08
MOT test number	736309202149
Result	✓ Passed
MOT #2	2012-04-13 17:32
MOT test number	719524202170
Result	✗ Failed
<div>Fail Offside Rear Lower coil spring incomplete (2.4.C.1a)</div>	
MOT #1	2011-04-20 12:32
MOT test number	418490211167
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
13 March 2024

✓

MOT

Expires:
28 November 2024

Tax status	Expired at 13 March 2024
Days left	48 days too late
MOT expiry date	28 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YS57HFX
Plate since	2019-03-29
Current registration	 YS57HFX
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-01-14
Last registration	2023-11-29
Complete history	See info



Registration #1	2008-01-14	12 mi
Registration #2	2011-04-20	52.079 mi
Registration #3	2012-04-13	54.216 mi
Registration #4	2012-04-18	54.254 mi
Registration #5	2013-04-06	56.705 mi
Registration #6	2014-03-29	59.489 mi
Registration #7	2015-04-04	62.026 mi
Registration #8	2016-04-05	64.047 mi
Registration #9	2017-03-18	66.105 mi
Registration #10	2018-03-09	67.915 mi
Registration #11	2018-03-09	67.915 mi
Registration #12	2019-03-09	69.915 mi
Registration #13	2019-03-09	71.915 mi
Registration #14	2019-03-09	73.915 mi
Registration #15	2019-03-09	75.915 mi
Registration #16	2019-03-09	77.915 mi
Registration #17	2019-03-09	79.915 mi
Registration #18	2019-03-09	81.915 mi
Registration #19	2019-03-09	83.915 mi
Registration #20	2019-03-09	85.915 mi
Registration #21	2019-03-09	87.915 mi
Registration #22	2019-03-09	89.915 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1504 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	17310665