




report date: 2024-03-29

General information

Make	SMART
Model	FORTWO COUPE PASSION 71
Colour	Black
Year of manufacture	2008
Top speed	90 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	13.3 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	52 kW / 71 HP / 71 BHP
Max. torque	92 Nm at 4.500 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	112 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-09-08
Pictures	28
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-20
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	30
Total items failed	13

MOT #19	2023-07-21 15:43
MOT test number	254986566902
Result	✓ Passed
Next expiry date	2024-07-20
Advice	Brake pipe corroded, covered in grease or other material All visible pipes (1.1.11 (c))

MOT #18	2023-07-20 10:53
MOT test number	398363716741
Result	✗ Failed
Fail	Offside Rear Service brake excessively binding (1.2.1 (f))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Brake pipe corroded, covered in grease or other material All visible pipes (1.1.11 (c))
Fail	Fuel cap/sealing device component leaking (6.1.3 (b) (i))

MOT #17	2022-06-13 07:49
MOT test number	892504564364
Result	✓ Passed

MOT #16	2021-02-04 10:50
MOT test number	893762844962
Result	✓ Passed

**MOT #15** 2020-01-13 13:33**MOT test number** 543066525884**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #14** 2020-01-09 11:03**MOT test number** 714054368310**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #13** 2018-12-04 13:23**MOT test number** 372655164546**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre wearing from the inside (5.2.3 (e))**MOT #12** 2018-12-03 13:39**MOT test number** 845452480622**Result** ✗ Failed**Fail** Offside Front Coil spring modified so the suspension is inoperative (5.3.1 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre wearing from the inside (5.2.3 (e))**MOT #11** 2017-10-10 13:19**MOT test number** 827948756572**Result** ✓ Passed

**MOT #10** 2016-07-04 14:02**MOT test number** 734734384146**Result** ✓ Passed**MOT #9** 2016-07-04 14:02**MOT test number** 873265241587**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #8** 2015-06-11 12:49**MOT test number** 278472265153**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Outer sill covers fitted**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #7** 2015-06-11 12:49**MOT test number** 645482965122**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Notice** Outer sill covers fitted**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #6** 2014-06-24 11:59**MOT test number** 847165474147**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Notice** Plastic outer sill covers fitted**MOT #5** 2013-07-02 15:21**MOT test number** 818773983149**Result** ✓ Passed**Notice** Vehicle underbody panels fitted**Advice** Offside Tyre worn close to the legal limit (4.1.E.1)**Notice** Plastic outer sill covers fitted**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-07-02 15:21**MOT test number** 247583083183**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Tyre worn close to the legal limit (4.1.E.1)**Notice** Plastic outer sill covers fitted**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Vehicle underbody panels fitted

**MOT #3** 2012-07-02 13:12**MOT test number** 249064682432**Result** ✓ Passed**Notice** Plastic outter sill covers fitted**Notice** Vehicle underbody panels fitted**MOT #2** 2012-07-02 13:12**MOT test number** 575144982113**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Plastic outter sill covers fitted**Notice** Vehicle underbody panels fitted**MOT #1** 2011-07-07 14:09**MOT test number** 408298181104**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
20 July 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this SMART. See if, where and when this SMART had damage and the car repair costs. We also check if this SMART was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SMART salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SMART in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SMART? How many owners did this SMART have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SMART had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this SMART is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SMART has been settled.

If not, and you buy this SMART then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SMART is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-07-14
Last registration	2023-07-21
Complete history	See info



Registration #1	2008-07-14	28 mi
Registration #2	2011-07-07	20.703 mi
Registration #3	2012-07-02	26.254 mi
Registration #4	2013-07-02	32.275 mi
Registration #5	2014-06-24	37.565 mi
Registration #6	2015-06-11	42.328 mi
Registration #7	2016-07-04	44.848 mi
Registration #8	2016-07-04	44.848 mi
Registration #9	2017-10-10	47.486 mi
Registration #10	2018-05-20	50.277 mi
Registration #11	2019-05-20	53.277 mi
Registration #12	2020-05-20	56.277 mi
Registration #13	2021-05-20	59.277 mi
Registration #14	2022-05-20	62.277 mi
Registration #15	2023-05-20	65.277 mi
Registration #16	2024-05-20	68.277 mi
Registration #17	2025-05-20	71.277 mi
Registration #18	2026-05-20	74.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1559 mm
Height	1542 mm
Length	2695 mm
Wheel base	1867 mm
Kerb weight	725 kg
Max. allowed weight	1020 kg

Additional information

Fuel tank capacity	33 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	3B21BD4139