





report date: 2024-03-29

General information

Make	FORD
Model	KA TITANIUM
Colour	Red
Year of manufacture	2015
Top speed	99 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	51 kW / 69 HP / 68 BHP	
Max. torque	102 Nm at 3.000 rpm	
Engine capacity	1.242 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	48.7 mpg	
Consumption extra urban	64.2 mpg	
Consumption combined	57.7 mpg	
CO2 emission	115 g/km	
CO2 label	С	



CarCheck.co.uk page 1/11



report date: 2024-03-29


Internet history

Entry 4

Date 2021-09-04

Pictures 59

Listing price <u>View report</u>









source: yesauto.com

Entry 3

Date 2021-08-19

Pictures 50

Listing price <u>View report</u>









source: heycar.co.uk

Entry 2


Date 2021-08-13

Pictures 59

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-08-02
Pictures	0

CarCheck.co.uk page 2/11

source: autotrader.co.uk



PN15LGK report date: 2024-03-29

MOT history

MOT #6

MOT expiry date	2024-09-22
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	5
Total items failed	5

MOT #9	2023-09-18 09:53
MOT test number	244575824166
Result	✓ Passed
Next expiry date 2024-09	
Advice Shock absorbers has slight external damage to the casing o/s rear is corroded (5.3.2 (b))	

MOT #8	2022-09-15 08:49
MOT test number	571416479802
Result	✓ Passed

MOT #7	2021-09-23 13:18
MOT test number	855704508048
Result	✓ Passed

MOT #6	2021-09-23 13:18
MOT test number	555683568876
Result	▼ Failed
Pass with rectification	Nearside Rear Tyre has a tear, caused by separation or partial failure of its

structure (5.2.3 (d) (ii))

MOT #5	2021-01-12 14:11
MOT test number	142488255054
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2021-01-12 10:52 142756091715 **MOT** test number Result × Failed Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Front Service brake binding but not excessively (1.2.1 (f)) Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail

MOT #3

MOT test number

S44971436993

Result

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #2

MOT test number

741017722744

Result

✓ Passed

MOT #1

2018-03-23 12:09

MOT test number

464298267497

Result

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 22 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	22 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



PN15LGK report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this FORD had different number plates. ober of plates faste since More info >

CarCheck.co.uk page 8/11



PN15LGK report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-03-26
Last registration	2023-09-18
Complete history	See info



Registration #1	2015-03-26	13 mi
Registration #2	2018-03-23	20.480 mi
Registration #3	2019-01-29	25.589 mi
Registration #4	2020-01-28	32.588 mi
Registration #5	2021-01-12	38.070 mi
Registration #6	2021-01-12	38.070 mi
Registration #7		9.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	840 kg

Additional information

Fuel tank capacity	35 I
Number of axles	2
Engine number	1361424

CarCheck.co.uk page 11/11