



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK320 CDI AVANTGARDE
Colour	Black
Year of manufacture	2005
Top speed	153 mph
0 - 60 mph	6.9 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.7 mpg
CO2 emission	195 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-05-12
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-22
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	15
Total items failed	18

MOT #21	2023-06-23 12:33
MOT test number	258858420884
Result	✓ Passed
Next expiry date	2024-06-22
Advice	Rear Sub-frame corroded but not seriously weakened Heavily coated in underseal (5.3.3 (b) (i))
Advice	Underside of vehicle showing signs of corrosion, heavily coated in underseal
Advice	Nearside Front Integral body structure is corroded but structural rigidity is not significantly reduced Floor pan (6.1.1 (c) (i))

**MOT #20**

2023-06-16 12:46

MOT test number

238964375955

Result**✗ Failed**

Advice Nearside Front Integral body structure is corroded but structural rigidity is not significantly reduced Floor pan (6.1.1 (c) (i))

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

Advice Rear Sub-frame corroded but not seriously weakened Heavily coated in underseal (5.3.3 (b) (i))

Fail Offside Rear Brake pipe excessively corroded Main center (1.1.11 (c))

Fail Nearside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))

Fail Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))

Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Underside of vehicle showing signs of corrosion, heavily coated in underseal

Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c))

Fail Nearside Rear Brake pipe excessively corroded Main center (1.1.11 (c))

**MOT #19** 2023-05-26 15:04**MOT test number** 803943893599**Result** ✗ Failed**Advice** Boot handle requires attention**Fail** Exhaust has a major leak of exhaust gases rear silencer (6.1.2 (a))**Advice** Oil leak, but not excessive front of engine? (8.4.1 (a) (i))**Fail** Emissions unable to be completed exhaust leak (8.2.2.2 (e))**MOT #18** 2022-06-09 14:26**MOT test number** 283898681663**Result** ✓ Passed**MOT #17** 2021-05-19 07:26**MOT test number** 489623961516**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2020-05-29 15:06**MOT test number** 548366568034**Result** ✓ Passed**MOT #15** 2019-12-07 09:54**MOT test number** 398294682197**Result** ✓ Passed



MOT #14	2018-12-07 08:50
----------------	------------------

MOT test number	308909908006
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #13	2017-12-09 10:05
----------------	------------------

MOT test number	975260741638
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2016-12-09 10:32
----------------	------------------

MOT test number	463468117729
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Rear Tyre worn close to the legal limit Both (4.1.E.1)
---------------	--

MOT #11	2015-11-20 09:15
----------------	------------------

MOT test number	697035620345
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2014-11-19 10:34
----------------	------------------

MOT test number	618033324307
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2013-11-20 12:33
---------------	------------------

MOT test number	248134023362
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
---------------	--

**MOT #8** 2013-11-20 12:33**MOT test number** 857094123306**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #7** 2012-12-01 12:15**MOT test number** 879766332360**Result** ✓ Passed**MOT #6** 2012-11-26 15:25**MOT test number** 515541632318**Result** ✗ Failed**Fail** Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #5** 2011-11-23 17:01**MOT test number** 446027021394**Result** ✓ Passed**MOT #4** 2011-11-22 15:03**MOT test number** 229766521389**Result** ✗ Failed**Fail** Offside Front coil spring fractured (2.4.C.1a)**MOT #3** 2010-11-23 13:03**MOT test number** 693967920342**Result** ✓ Passed



MOT #2	2009-12-01 10:23
MOT test number	530935239375
Result	✓ Passed

MOT #1	2008-12-08 15:01
MOT test number	160833848300
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
22 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 LM55BYD
Plate since	2024-03-29
Current registration	 LM55BYD
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-12-18
Last registration	2023-06-23
Complete history	See info



Registration #1	2005-12-18	15 mi
Registration #2	2008-12-08	26.187 mi
Registration #3	2009-12-01	33.275 mi
Registration #4	2010-11-23	39.062 mi
Registration #5	2011-11-22	45.038 mi
Registration #6	2011-11-23	45.038 mi
Registration #7	2012-11-26	58.077 mi
Registration #8	2012-12-01	58.160 mi
Registration #9	2013-11-20	63.504 mi
Registration #10	2014-11-19	68.432 mi
Registration #11	2015-11-20	72.913 mi
Registration #12	2016-11-20	75.277 mi
Registration #13	2017-11-20	75.277 mi
Registration #14	2018-11-20	75.277 mi
Registration #15	2019-11-20	75.277 mi
Registration #16	2020-11-20	75.277 mi
Registration #17	2021-11-20	75.277 mi
Registration #18	2022-11-20	75.277 mi
Registration #19	2023-11-20	75.277 mi
Registration #20	2024-11-20	75.277 mi
Registration #21	2025-11-20	75.277 mi
Registration #22	2026-11-20	75.277 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1660 kg
Max. allowed weight	2115 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	64291040044370