



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	AVENSIS D-4D TR
Colour	Blue
Year of manufacture	2010
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	140 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-06-05
Pictures	34
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2025-02-01
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	27
Total items failed	13

MOT #15 2024-01-09 10:39**MOT test number** 805854423117**Result** ✓ Passed**Next expiry date** 2025-02-01

- Advice** Engine cover and under tray fitted obscuring some components
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

MOT #14 2023-02-02 09:51**MOT test number** 315917442998**Result** ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**MOT #13**

2022-03-30 16:37

MOT test number

614285420330

Result

✓ Passed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Number plate lights modified**Advice** Rear Service brake grabbing slightly (1.2.1 (c))**Advice** Under tray fitted**MOT #12**

2022-03-29 15:54

MOT test number

939983265581

Result

✗ Failed

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Under tray fitted**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Electronic parking brake warning indicates a malfunction (1.1.6 (e))**Fail** Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))

**MOT #11**

2020-12-11 11:50

MOT test number

613642907163

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10

2020-12-11 11:50

MOT test number

116954528577

Result

✗ Failed

- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

MOT #9

2019-11-11 09:42

MOT test number

100594818376

Result

✓ Passed

- Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #8** 2018-11-09 14:49**MOT test number** 187548929995**Result** ✓ Passed**MOT #7** 2017-10-30 14:39**MOT test number** 314396843984**Result** ✓ Passed**MOT #6** 2016-10-31 14:12**MOT test number** 441361275652**Result** ✓ Passed**MOT #5** 2016-10-31 14:11**MOT test number** 306043129778**Result** ✗ Failed**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2015-10-28 00:00**MOT test number** 169708021497**Result** ✓ Passed**MOT #3** 2014-08-13 10:02**MOT test number** 376275224264**Result** ✓ Passed**MOT #2** 2013-09-11 15:06**MOT test number** 955804653294**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside front tyre as 10mm cut in wall



MOT #1	2013-09-11 15:06
MOT test number	156354553205
Result	✗ Failed
Notice	Nearside front tyre as 10mm cut in wall
Pass with rectification	Front registration plate deteriorated (6.3.1d)
Advice	Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
1 February 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YD60FZU
Plate since	2019-03-29
Current registration	YD60FZU
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-16
Last registration	2024-01-09
Complete history	See info



Registration #1	2010-09-16	6 mi
Registration #2	2013-09-11	108.983 mi
Registration #3	2014-08-13	135.298 mi
Registration #4	2015-10-28	145.783 mi
Registration #5	2016-10-31	154.514 mi
Registration #6	2016-10-31	154.514 mi
Registration #7	2017-10-30	162.876 mi
Registration #8	2018-11-09	173.768 mi
Registration #9	2019-01-01	20,000 (approx.)
Registration #10	2019-01-01	20,000 (approx.)
Registration #11	2019-01-01	20,000 (approx.)
Registration #12	2019-01-01	20,000 (approx.)
Registration #13	2019-01-01	20,000 (approx.)
Registration #14	2019-01-01	20,000 (approx.)
Registration #15	2019-01-01	20,000 (approx.)
Registration #16	2019-01-01	20,000 (approx.)

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1480 mm
Length	4765 mm
Wheel base	2700 mm
Kerb weight	1450 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1AD5543711