





report date: 2024-03-28

#### General information

| Make                | FORD              |
|---------------------|-------------------|
| Model               | MONDEO ZETEC TDCI |
| Colour              | Silver            |
| Year of manufacture | 2009              |
| Top speed           | 124 mph           |
| 0 - 60 mph          | 10.4 seconds      |
| Gearbox             | 5 speed Manual    |

### Engine & fuel consumption

| Power                   | 125 BHP             |
|-------------------------|---------------------|
| Max. torque             | 320 Nm at 1.800 rpm |
| Engine capacity         | 1.753 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 38.7 mpg            |
| Consumption extra urban | 61.4 mpg            |
| Consumption combined    | 50.4 mpg            |
| CO2 emission            | 149 g/km            |
| CO2 label               | F                   |



CarCheck.co.uk page 1/13



report date: 2024-03-28

# Internet history

#### Entry 1

Date 2021-07-07

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

| B 4   | $\sim$ $-$  |      |        |
|-------|-------------|------|--------|
| 10.71 | $^{\prime}$ | hic  | tory   |
| 101   | C I         | 1115 | I OI V |
|       | •           |      | ,      |

| MOT expiry date    | 2025-01-30 |
|--------------------|------------|
| MOT pass rate      | 72 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 5          |
| Total advice items | 8          |
| Total items failed | 6          |

| MOT #18          | 2024-01-31 11:43 |
|------------------|------------------|
| MOT test number  | 972955577970     |
| Result           | <b>✓</b> Passed  |
| Next expiry date | 2025-01-30       |

| MOT #17   | 2024-01-22 12:57 |
|---|------------------|
| MOT test number   | 411535119253     |
| Result  | <b>×</b> Failed  |
| Fail Nearside Rear Sub-frame pin or bush excessively worn (5.3.4 (a) (i)) |                  |

| MOT #16         | 2023-01-31 12:06 |
|-----------------|------------------|
| MOT test number | 943982955774     |
| Result          | <b>✓</b> Passed  |
|                 |                  |

| MOT test number   | 943962933774     |
|---|------------------|
| Result  | <b>✓</b> Passed  |
|   |                  |
| MOT #15   | 2023-01-31 09:49 |
| MOT test number   | 843185112993     |
| Result  | <b>×</b> Failed  |
| Fail Nearside Rear Tyre tread depth below requirements of 1.6mm 205/55/R16 (5.2 | 2.3 (e))         |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))     |                  |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))   |                  |

CarCheck.co.uk page 3/13



report date: 2024-03-28

| MOT #14  |  | 2022-04-19 14:00 |
|----------|--|------------------|
| MOT test | number   | 169618839814     |
| Result   |  | ✓ Passed         |
|          |  |                  |
| MOT #13  |  | 2022-04-14 09:54 |
| MOT test | number   | 474257458978     |
| Result   |  | <b>×</b> Failed  |
| Advice   | Nearside Front Tyre wearing on inner and outer edges |                  |
| Advice   | Offside Front Tyre wearing on inner edge             |                  |
|          | 55 1 2 5 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1             | - 2 4 ( ) ('))   |

| Fail Offside Rear Suspension arm pin or bush excessively worn Trailing arm bush (5.3.4 (a) (i)) |                  |  |
|---|------------------|--|
|   |                  |  |
| MOT #12   | 2021-07-07 12:44 |  |
| MOT test number   | 159043133805     |  |
| Result  | √ Passed         |  |
|   |                  |  |
| MOT #11   | 2020-06-22 15:02 |  |
| MOT test number   | 519418750994     |  |
| Result  | ✓ Passed         |  |
|   |                  |  |
| MOT #10   | 2019-03-19 11:29 |  |
| MOT test number   | 622594584692     |  |
| Result  | ✓ Passed         |  |
|   |                  |  |
| MOT #9  | 2018-03-19 11:00 |  |
| MOT test number   | 864467106435     |  |
| Result  | ✓ Passed         |  |

CarCheck.co.uk page 4/13



report date: 2024-03-28

| MOT #8                       | 2017-04-05 09:20 |
|------------------------------|------------------|
| MOT test number              | 312128761106     |
| Result                       | <b>✓</b> Passed  |
| Advice Front front tyres low |                  |

| MOT #7   | 2016-04-13 13:16 |
|--|------------------|
| MOT test number  | 504115080141     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #6   | 2015-10-26 15:22 |
| MOT test number  | 701443408388     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #5   | 2015-10-26 15:22 |
| MOT test number  | 988250415619     |
| Result   | <b>X</b> Failed  |
| Pass with rectification Offside Stop lamp not working (1.2.1b) |                  |

| MOT #4          | 2014-11-08 11:06 |
|-----------------|------------------|
| MOT test number | 426522714452     |
| Result          | <b>✓</b> Passed  |

| MOT #3  | 2014-11-08 09:05 |
|---|------------------|
| MOT test number   | 488782414424     |
| Result  | <b>≍</b> Failed  |
| Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)  |                  |
| Notice Under-trays fitted obscuring some underside components   |                  |
| Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) |                  |

CarCheck.co.uk page 5/13



EA59NTV report date: 2024-03-28

MOT #2

MOT test number

429453513466

Result

Notice N/s/f tyre has a cut on outer sidewall

MOT #1

MOT test number

Result

Notice Advise inspection limited due to undertrays fitted

2012-11-10 12:34

886765012375

✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

## Tax & MOT check



| Tax status       | Valid until 1 July |
|------------------|--------------------|
| Days left        | 64                 |
| MOT expiry date  | 30 January 2025    |
| Full MOT history | See MOT history    |

#### Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | F          |
| Single payment (12 months)              | £ 200,00,- |
| Single six month payment                | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

## Owner history

| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is  |             |
|--|-------------|
|  |             |
| HARMAN CONTRACTOR CONT |             |
|  |             |
| ***************************************  |             |
| *******  |             |
|  |             |
| ***************************************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this FORD had different number plates.  |             |
| Number of plates   | ,           |
| Current registration   | UK UK       |
| Plate since  |             |
| Current registration   | OK SIE      |
| Plate since  |             |
|  | More info > |

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 20         |
| First mileage registration | 2009-11-12 |
| Last registration          | 2024-01-31 |
| Complete history           | See info   |



| Registration #1  | 2009-11-12 | 19 mi     |
|------------------|------------|-----------|
| Registration #2  | 2012-11-10 | 18.561 mi |
| Registration #3  | 2013-11-09 | 23.080 mi |
| Registration #4  | 2014-11-08 | 29.589 mi |
| Registration #5  | 2014-11-08 | 29.589 mi |
| Registration #6  | 2015-10-26 | 35.437 mi |
| Registration #7  | 2015-10-26 | 35.437 mi |
| Registration #8  | 2016-04-13 | 36.313 mi |
| Registration #9  | 2017-04-05 | 46.257 mi |
| Registration #10 | 2018-03-19 | 56.476 mi |
| Registration #11 |            | 71.777 es |
| Registration #12 |            | 77.777 44 |
| Registration #13 |            | 11.177 es |
| Registration #14 |            | 71.777 es |
| Registration #15 |            | 11.177 es |
| Registration #16 |            | 11.777 es |
| Registration #17 |            | 11.177 es |
| Registration #18 |            | 11.777 es |
| Registration #19 |            | 11.177 es |
| Registration #20 |            | 11.777 es |
|                  |            |           |

More info >

CarCheck.co.uk page 12/13



EA59NTV report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 2078 mm |
|---------------------|---------|
| Height              | 1451 mm |
| Length              | 4778 mm |
| Wheel base          | 2754 mm |
| Kerb weight         | 1505 kg |
| Max. allowed weight | 2150 kg |

# Additional information

| Fuel delivery                     | Direct Injection |            |
|-----------------------------------|------------------|------------|
| Number of doors                   | 5                |            |
| Number of seats                   | 5                |            |
| Number of axles<br>Carcheck.co.uk | 2                | page 13/13 |