



report date: 2024-03-28

General information

Make	CITROEN
Model	C2 DESIGN
Colour	Black
Year of manufacture	2006
Top speed	98 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.200 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-07-24
Pictures	7
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-03
Pictures	7
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-09-06
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	21
Total items failed	11

MOT #18 2023-09-07 13:12

MOT test number 251408454722

Result ✓ Passed

Next expiry date 2024-09-06

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Exhaust mounting defective box bracket (6.1.2 (a))
- Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Advice** Front Direction indicator slightly discoloured both (4.4.3 (a))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17 2021-06-30 15:44

MOT test number 731145933141

Result ✓ Passed

**MOT #16** 2020-06-29 10:58**MOT test number** 961777198173**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2019-06-27 11:52**MOT test number** 809330631360**Result** ✓ Passed**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**MOT #14** 2019-06-27 11:52**MOT test number** 634987739592**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #13** 2018-06-25 10:47**MOT test number** 665959710286**Result** ✓ Passed**MOT #12** 2018-06-25 10:47**MOT test number** 734218461626**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))



**MOT #11** 2017-06-26 09:07**MOT test number** 489513943729**Result** ✓ Passed**Advice** Both rear tyres starting to split**MOT #10** 2016-06-28 10:54**MOT test number** 562663852393**Result** ✓ Passed**Advice** Nearside Rear tyre side wall starting to split**MOT #9** 2016-06-16 11:42**MOT test number** 732133002296**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Offside Rear Direction indicator not working (1.4.A.2c)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear tyre side wall starting to split**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**MOT #8** 2015-06-29 12:36**MOT test number** 589630785120**Result** ✓ Passed

**MOT #7** 2014-06-27 12:13**MOT test number** 825568074113**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-06-27 12:13**MOT test number** 806928274118**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2013-06-27 12:48**MOT test number** 845628973187**Result** ✓ Passed**MOT #4** 2012-06-28 10:42**MOT test number** 216650282123**Result** ✓ Passed**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #3** 2011-06-30 10:14**MOT test number** 188201581185**Result** ✓ Passed



MOT #2	2010-06-30 16:59
MOT test number	264661180134
Result	✓ Passed

MOT #1	2009-07-08 10:37
MOT test number	642069989151
Result	✓ Passed

**Notice** Both front wipers split





Tax & MOT check

X

Untaxed

Tax expired:  
1 April 2024

✓

MOT

Expires:  
6 September 2024

Tax status	Expired at 1 April 2024
Days left	29 days too late
MOT expiry date	6 September 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-06-30
Last registration	2023-09-07
Complete history	<a href="#">See info</a>



Registration #1	2006-06-30	16 mi
Registration #2	2009-07-08	12.159 mi
Registration #3	2010-06-30	16.826 mi
Registration #4	2011-06-30	20.222 mi
Registration #5	2012-06-28	23.769 mi
Registration #6	2013-06-27	27.132 mi
Registration #7	2014-06-27	31.115 mi
Registration #8	2015-06-29	34.118 mi
Registration #9	2016-06-16	36.607 mi
Registration #10	2016-06-28	36.654 mi
Registration #11	2016-06-28	36.654 mi
Registration #12	2016-06-28	36.654 mi
Registration #13	2016-06-28	36.654 mi
Registration #14	2016-06-28	36.654 mi
Registration #15	2016-06-28	36.654 mi
Registration #16	2016-06-28	36.654 mi
Registration #17	2016-06-28	36.654 mi
Registration #18	2016-06-28	36.654 mi
Registration #19	2016-06-28	36.654 mi
Registration #20	2016-06-28	36.654 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	932 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7T4809007