



CITROËN




report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI AIRDREAM DSPORT
Colour	Black
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 2

Date	2022-11-29
Pictures	0
Listing price	View report

source: carcraft.co.uk



MOT history

MOT expiry date	2024-11-08
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	9
Total items failed	15

MOT #13	2023-10-30 12:32
MOT test number	855032453162
Result	✓ Passed
Next expiry date	2024-11-08

MOT #12	2022-11-09 14:41
MOT test number	913453864816
Result	✓ Passed

MOT #11	2022-11-07 15:38
MOT test number	800570292915

Result	✗ Failed
Fail	Nearside Front Suspension component mounting prescribed area is inadequately repaired (5.3.6 (a) (i))
Advice	Exhaust mounting defective (6.1.2 (a))
Fail	Nearside Rear Seat belt webbing significantly weakened (7.1.2 (b) (ii))
Fail	Central Rear Seat belt buckle missing (7.1.2 (d))
Fail	Offside Front Suspension component mounting prescribed area is inadequately repaired (5.3.6 (a) (i))

MOT #10	2022-04-26 08:06
MOT test number	927360506453
Result	✓ Passed



MOT #9	2022-04-22 14:54
MOT test number	374450813047
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Lower Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt drop link gaiters r split top and bottom (5.3.4 (b) (ii))

MOT #8	2021-10-13 16:29
MOT test number	638208937664
Result	✓ Passed
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7	2020-01-09 16:19
MOT test number	120642033584
Result	✓ Passed



MOT #6 2020-01-08 10:34

MOT test number 555614369433

Result ✗ Failed

- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge both sides, heavily worn on inner edges (5.2.3 (e))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #5 2018-11-05 11:21

MOT test number 608808589378

Result ✓ Passed

MOT #4 2016-11-19 11:00

MOT test number 891619550222

Result ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3 2016-11-18 10:51

MOT test number 507389069094

Result ✗ Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2015-11-27 13:15

MOT test number 520030712037

Result ✓ Passed

MOT #1 2015-08-03 09:32

MOT test number 949355315253

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 December 2024

✓
MOT

Expires:
8 November 2024

Tax status Valid until 1 December

Days left 217

MOT expiry date 8 November 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable




Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	BK62VZL
Plate since	2019-09-29
Current registration	BK62VZL
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-10-13
Last registration	2023-10-30
Complete history	See info



Registration #1	2012-10-13	6 mi
Registration #2	2015-08-03	23.747 mi
Registration #3	2015-11-27	25.541 mi
Registration #4	2016-11-18	33.648 mi
Registration #5	2016-11-19	33.656 mi
Registration #6	2018-11-05	42.536 mi
Registration #7	2020-01-08	55.110 mi
Registration #8	2020-01-09	55.149 mi
Registration #9	2020-01-09	55.149 mi
Registration #10	2020-01-09	55.149 mi
Registration #11	2020-01-09	55.149 mi
Registration #12	2020-01-09	55.149 mi
Registration #13	2020-01-09	55.149 mi
Registration #14	2020-01-09	55.149 mi
Registration #15	2020-01-09	55.149 mi

[More info >](#)



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBEF3023664