





report date: 2024-03-28

General information

Make	KIA
Model	RIO 16V
Colour	Black
Year of manufacture	2009
Top speed	110 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-05-23

Pictures 39

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-09-11
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	25
Total items failed	1

MOT #13		2023-09-05 09:07
MOT test	number	255269347261
Result		✓ Passed
Next expi	ry date	2024-09-11
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Surface corrosion on rear suspension components.	
Advice	Brake pipe corroded, covered in grease or other material Front to rear. (1.1.11 (c	:))
Advice	Front crossmember corroded.	
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Front subframe corroded.	

MOT #12		2022-09-08 09:57
MOT test	number	366027544715
Result		✓ Passed
Advice	Offside Front headlight leveler slow to react	
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Park brake lever , free travel	

CarCheck.co.uk page 3/13



GJ59DYB

MOT #11 2021-09-07 11:25

MOT test number 170452607190

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2021-09-07 11:25

MOT test number 360176224250

Result X Failed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2020-08-15 10:44

MOT test number 355977797931

Result

Passed

Advice Power steering close to minimum mark (2.1.5 (b) (i))

Advice Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

(ii))

MOT #8 2019-09-03 15:07

MOT test number 683031063143

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking on inner sidewall (5.2.3 (d)

CarCheck.co.uk page 4/13



MOT #7 2018-08-24 09:10

MOT test number 974627092161

Result ✓ Passed

Advice

tread.

Both front tyres worn completely down on the very edges of the treads, not deemed to be primary

MOT #6 2017-09-05 12:06

MOT test number 759211237937

Result
✓ Passed

MOT #5 2016-08-26 08:14

MOT test number 722371565138

Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #4 2015-09-03 00:00

MOT test number 375851564437

Result ✓ Passed

MOT #3 2014-08-20 10:42

MOT test number 148212534208

Result

Passed

MOT #2 2013-09-06 15:09

MOT test number 778339943270

Result

Passed

Notice All tyres are starting to perish

Notice Both nearside tyres are wearing on edge

CarCheck.co.uk page 5/13



MOT #1

MOT test number

Result

Notice Front wipers smearing the screen slightly

2012-08-20 10:20

356243832273

✓ Passed

CarCheck.co.uk page 6/13





Tax & MOT check



Tax status	Valid until 1 May
Days left	368
MOT expiry date	11 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owr	200	oict	001
T DVVI	161 1	11151	$\mathbf{n} \mathbf{v}$
		1130	. O i y

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this KIA had different number plates.			
See in this check if this KIA had different number plates.			
See in this check if this KIA had different number plates.			
See in this check if this KIA had different number plates.			
See in this check if this KIA had different number plates.			
See in this check if this KIA had different number plates.			
See in this check if this KIA had different number plates.	manage of the same		
See in this check if this KIA had different number plates.	***************************************		
See in this check if this KIA had different number plates.	*************		
See in this check if this KIA had different number plates.		More info	>
器	Plate changes		
	See in this check if this KIA had different number plates.		
	Number of plates		,
Plate since	Current registration	NK NK	
Plate since	Plate since		
More info >	Current registration	UK UK	
More info >	Plate since		
		More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-11
Last registration	2023-09-05
Complete history	See info



Registration #1	2009-09-11	11 mi
Registration #2	2012-08-20	22.445 mi
Registration #3	2013-09-06	30.079 mi
Registration #4	2014-08-20	37.666 mi
Registration #5	2015-09-03	45.627 mi
Registration #6	2016-08-26	52.498 mi
Registration #7	2017-09-05	63.114 mi
Registration #8	2018-08-24	69.281 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 12/13




Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1154 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number G4EE9H252216