





### General information

Make	HYUNDAI
Model	140 CRDI PREMIUM BLUE DRIVE
Colour	Silver
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.3 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	С







## Internet history

Entry 1		
Date	2021-06-28	
Pictures	9	
Listing price	View report	









source: autotrader.co.uk



## MOT history

MOT expiry date	2024-11-25
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #11	2023-11-23 12:39
MOT test number	672390981050
Result	🗸 Passed
Next expiry date	2024-11-25
Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))	

MOT #10	2022-11-25 13:08
MOT test number	822305599610
Result	✓ Passed

MOT #9	2021-11-26 12:33
MOT test number	155678411499
Result	✓ Passed

MOT #8	2021-11-23 14:17
MOT test number	201024142110
Result	🗙 Failed
<b>Fail</b> Offside Front Track rod end ball joint has excessive play dangerous (2.1.3 (b) (i))	

MOT #7	2020-11-26 11:28
MOT test number	758751974630
Result	✓ Passed



MOT #6		2020-11-23 11:19
MOT test n	umber	505272928820
Result		🗙 Failed
Advice	Nearside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))	
Fail Ne	arside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #5	2019-11-15 15:56
MOT test number	135253127463
Result	✓ Passed
Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Rear Tyre worn on inner edge	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Rear Tyre wearing on inner edge	

MOT #4	2018-11-16 10:30
MOT test number	357794811997
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm and low of	on edges (5.2.3 (e))
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)	)
Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm and low	on edges (5.2.3 (e))

MOT #3	2017-12-20 14:29
MOT test number	835234105595
Result	✓ Passed



B	D	6	3	V	V	D	F
	rep	ort	dat	te:	202	24-0	3-28

MOT #2	2017-06-06 16:57
MOT test number	275325267377
Result	🗸 Passed
MOT #1	2017-01-10 11:01
MOT test number	139615095001
Result	Passed
Advice Front Brake pad(s) wearing thin approx 2mm (3.5.1g)	



Tax & MOT check

<b>Tax due:</b> 1 July 2024	✓ Taxed	✓ MOT Expires: 25 November 2024	
Tax status		Valid u	ntil 1 July
Days left			62
MOT expiry date		25 Nove	mber 2024
Full MOT history		<u>See M</u>	<u>IOT history</u>
Tax calculation			

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	VAMPL
Date	······································
Category	AMP
Туре	

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here.

and the second se	
**********	
*******	
******	
*********	
*******	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



BD63WDF report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-01-23
Last registration	2023-11-23
Complete history	See info



Registration #1	2014-01-23	8 mi
Registration #2	2017-01-10	79.757 mi
Registration #3	2017-06-06	85.254 mi
Registration #4	2017-12-20	85.259 mi
Registration #5	2018-11-16	116.725 mi
Registration #6	2019-11-15	150.738 mi
Registration #7	2020-11-23	182.130 mi
Registration #8		11.777 esi
Registration #9		11.777 esi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.117 mi





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
\$0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1638 kg
Max. allowed weight	2120 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12