



DPIOKWL

report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | FORD |
| Model | FIESTA ZETEC |
| Colour | Blue |
| Year of manufacture | 2010 |
| Top speed | 104 mph |
| 0 - 60 mph | 13.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-----------------|----------|
| Power | 81 BHP |
| Max. torque | 114 Nm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| CO2 emission | 133 g/km |
| CO2 label | E |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-14 |
| MOT pass rate | 92 % |
| MOT passed | 12 |
| Failed MOT tests | 1 |
| Total advice items | 26 |
| Total items failed | 8 |

| | |
|------------------|--|
| MOT #13 | 2024-04-12 08:31 |
| MOT test number | 256807878599 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-14 |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |
| Advice | Play in steering rack inner joint(s) |
| Advice | Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) |
| Advice | Battery was flat on arrival |
| Advice | Suspension component pin or bush slightly worn Both rear axle bushes (5.3.4 (a) (i)) |

**MOT #12**

2024-04-09 08:18

MOT test number

478244496882

Result**✗ Failed**

- Fail** Offside Headlamp light source and lamp not compatible Aftermarket hid fitted (4.1.4 (c))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Offside Rear Seat belt buckle missing (7.1.2 (d))
- Fail** Nearside Front Headlamp light source and lamp not compatible Aftermarket hid fitted (4.1.4 (c))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 175/64/14 (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Suspension component pin or bush slightly worn Both rear axle bushes (5.3.4 (a) (i))
- Advice** Battery was flat on arrival
- Fail** Central Rear Seat belt buckle missing (7.1.2 (d))

MOT #11

2023-04-15 11:51

MOT test number

917218844952

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10** 2022-02-26 12:13**MOT test number** 392054244029**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2021-03-03 13:02**MOT test number** 984361356418**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge nearside front & offside front (5.2.3 (e))**MOT #8** 2019-10-19 08:00**MOT test number** 142026791949**Result** ✓ Passed**Advice** Exhaust heat shield**Advice** Front Inner tyre edges worn**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement axle (5.3.4 (a) (i))**Advice** Eng oil on min**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #7** 2018-10-22 08:21**MOT test number** 622252692695**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2017-10-14 07:57**MOT test number** 662811580953**Result** ✓ Passed

**MOT #5** 2016-10-31 10:19**MOT test number** 797251860289**Result** ✓ Passed**MOT #4** 2016-04-06 09:03**MOT test number** 529937833661**Result** ✓ Passed**Advice** Slight hesitation from engine during emissions test**MOT #3** 2015-04-01 10:23**MOT test number** 387271295075**Result** ✓ Passed**MOT #2** 2014-03-25 11:44**MOT test number** 938434184080**Result** ✓ Passed**Notice** Oil leak**Notice** Front tyres starting to perish in tread.**Notice** Vehicle's internal headlight adjuster altered to recheck lights**MOT #1** 2013-04-08 12:14**MOT test number** 609058093075**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
14 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 14 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | DP10KWL |
| Plate since | 2019-03-28 |
| Current registration | DP10KWL |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2010-06-30 |
| Last registration | 2024-04-12 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-06-30 | 22 mi |
| Registration #2 | 2013-04-08 | 20.693 mi |
| Registration #3 | 2014-03-25 | 27.361 mi |
| Registration #4 | 2015-04-01 | 34.787 mi |
| Registration #5 | 2016-04-06 | 44.152 mi |
| Registration #6 | 2016-10-31 | 49.000 mi |
| Registration #7 | 2017-10-14 | 56.900 mi |
| Registration #8 | 2018-05-22 | 65.277 mi |
| Registration #9 | 2019-05-22 | 75.277 mi |
| Registration #10 | 2020-05-22 | 85.277 mi |
| Registration #11 | 2021-05-22 | 95.277 mi |
| Registration #12 | 2022-05-22 | 105.277 mi |
| Registration #13 | 2023-05-22 | 115.277 mi |
| Registration #14 | 2024-05-22 | 125.277 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1722 mm |
| Height | 1433 mm |
| Length | 3950 mm |
| Wheel base | 2489 mm |
| Kerb weight | 1109 kg |
| Max. allowed weight | 1495 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 42 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|---------------|---------|
| Engine number | 9E46444 |
|---------------|---------|