



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D3 SE LUX AWD
Colour	Blue
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-22
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-08
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	20
Total items failed	7

MOT #132023-10-09 09:04

MOT test number531112545524

Result✓ Passed

Next expiry date2024-10-08

- Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Engine covers fitted
- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Undertrays fitted

MOT #122022-10-04 11:14

MOT test number921862444923

Result✓ Passed

**MOT #11** 2022-10-04 11:14**MOT test number** 801200778333**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #10** 2021-09-22 07:21**MOT test number** 261150589683**Result** ✓ Passed**MOT #9** 2020-10-05 16:58**MOT test number** 546674058227**Result** ✓ Passed**MOT #8** 2019-10-04 13:49**MOT test number** 458325522929**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #7** 2019-09-28 09:47**MOT test number** 665463470201**Result** ✗ Failed**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Headlamp levelling device inoperative (4.1.5 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Side repeater incorrect colour (4.4.3 (a))

**MOT #6** 2018-09-20 15:05**MOT test number** 426658744350**Result** ✓ Passed**MOT #5** 2017-09-29 14:36**MOT test number** 429723750232**Result** ✓ Passed**MOT #4** 2017-09-29 10:35**MOT test number** 282066491004**Result** ✗ Failed**Fail** Nearside Side repeater not working (1.4.A.2c)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #3** 2016-09-08 13:45**MOT test number** 410277905610**Result** ✓ Passed**Advice** All four tyre valves are slightly deteriorated**MOT #2** 2016-09-08 13:45**MOT test number** 580836757238**Result** ✗ Failed**Advice** All four tyre valves are slightly deteriorated**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)



MOT #1	2015-10-08 14:26
MOT test number	609668798104
Result	✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Front tyres wearing on inner edges



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
8 October 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	217
<b>MOT expiry date</b>	8 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-10-07
Last registration	2023-10-09
Complete history	<a href="#">See info</a>



Registration #1	2011-10-07	12 mi
Registration #2	2015-10-08	75.233 mi
Registration #3	2016-09-08	86.654 mi
Registration #4	2016-09-08	86.654 mi
Registration #5	2017-09-29	98.076 mi
Registration #6	2017-09-29	98.076 mi
Registration #7	2018-09-20	110.044 mi
Registration #8	2019-09-28	121.702 mi
Registration #9	2020-09-28	133.364 mi
Registration #10	2021-09-28	145.026 mi
Registration #11	2022-09-28	156.688 mi
Registration #12	2023-09-28	168.350 mi
Registration #13	2024-09-28	180.012 mi
Registration #14	2025-09-28	191.674 mi
Registration #15	2026-09-28	203.336 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1863 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1058754