



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK200K AVANTGARDE
Colour	Silver
Year of manufacture	2007
Top speed	142 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 4.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	207 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-01
Pictures	25
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-12
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	21
Total items failed	3

MOT #18	2024-03-14 10:01
MOT test number	292999838368
Result	✓ Passed
Next expiry date	2025-04-12
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

MOT #17	2023-04-13 14:10
MOT test number	586516537923
Result	✓ Passed

MOT #16	2022-08-01 15:38
MOT test number	417919313033
Result	✓ Passed
Advice	Offside Front Lower Suspension arm ball joint has slight play rear joint (5.3.4 (a) (i))

MOT #15	2021-07-27 14:36
MOT test number	996928807411
Result	✓ Passed

**MOT #14** 2020-10-10 08:55**MOT test number** 981876906994**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2019-10-21 14:46**MOT test number** 329974917140**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2019-03-13 11:41**MOT test number** 154710218531**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge measured approx 2mm (5.2.3 (e))**Advice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge measured approx 2mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Undertrays fitted obscuring some components under the vehicle

**MOT #11** 2019-03-11 09:38**MOT test number** 676697144675**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge measured approx 2mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Undertrays fitted obscuring some components under the vehicle**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge measured approx 2mm (5.2.3 (e))**MOT #10** 2018-03-22 12:26**MOT test number** 382203678892**Result** ✓ Passed**MOT #9** 2017-03-22 15:01**MOT test number** 798645138519**Result** ✓ Passed**MOT #8** 2016-03-24 12:55**MOT test number** 580408542309**Result** ✓ Passed**MOT #7** 2015-03-19 14:49**MOT test number** 129588775004**Result** ✓ Passed



MOT #6	2014-03-18 15:29
---------------	------------------

MOT test number	515597274030
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2013-03-21 14:47
---------------	------------------

MOT test number	655430683040
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2012-02-28 14:24
---------------	------------------

MOT test number	285419652002
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2012-02-28 14:24
---------------	------------------

MOT test number	397639652091
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Front Headlamp not working on dipped beam (1.7.5a)
--------------------------------	---

MOT #2	2011-03-18 13:14
---------------	------------------

MOT test number	125997371464
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2010-03-05 11:55
---------------	------------------

MOT test number	851294160086
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
12 April 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	12 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 GV07MFA
Plate since	2024-03-29
Current registration	 GV07MFA
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-27
Last registration	2024-03-14
Complete history	See info



Registration #1	2007-03-27	6 mi
Registration #2	2010-03-05	27.571 mi
Registration #3	2011-03-18	30.579 mi
Registration #4	2012-02-28	33.716 mi
Registration #5	2013-03-21	36.946 mi
Registration #6	2014-03-18	40.674 mi
Registration #7	2015-03-19	43.679 mi
Registration #8	2016-03-24	46.471 mi
Registration #9	2017-03-22	48.445 mi
Registration #10	2018-03-22	49.988 mi
Registration #11	2019-03-22	51.531 mi
Registration #12	2020-03-22	53.074 mi
Registration #13	2021-03-22	54.617 mi
Registration #14	2022-03-22	56.160 mi
Registration #15	2023-03-22	57.703 mi
Registration #16	2024-03-14	59.246 mi
Registration #17	2024-03-14	60.789 mi
Registration #18	2024-03-14	62.332 mi
Registration #19	2024-03-14	63.875 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1615 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27194030838625