



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	B-CLASS B150 SE
Colour	Black
Year of manufacture	2008
Top speed	108 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	140 Nm at 4.000 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-09
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-25
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	34
Total items failed	5

MOT #16 2023-10-25 13:38

MOT test number 314504396393

Result ✓ Passed

Next expiry date 2024-10-25

Advice Offside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Minor Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #15 2022-10-26 15:02

MOT test number 628965974130

Result ✓ Passed

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2022-10-26 10:20

MOT test number

117948659615

Result**✗ Failed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Steering linkage ball joint has excessive play (2.1.3 (b) (i))**MOT #13**

2021-06-09 13:06

MOT test number

532261130436

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #12**

2021-06-09 13:06

MOT test number

601121125258

Result**✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #11**

2020-05-27 10:27

MOT test number

511671897942

Result

✓ Passed

Advice Offside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10**

2019-06-06 12:36

MOT test number

164998632389

Result

✓ Passed

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2019-06-06 09:32

MOT test number

475988715505

Result

✗ Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8**

2018-06-11 13:32

MOT test number

739266570762

Result

✓ Passed

Advice Nearside front anti roll bar link has slight play in a ball joint**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside constant velocity joint gaiter leaking slightly

**MOT #7** 2017-10-28 10:13**MOT test number** 533661849096**Result** ✓ Passed**MOT #6** 2016-10-22 11:22**MOT test number** 396150789390**Result** ✓ Passed**MOT #5** 2015-10-24 10:42**MOT test number** 554616521616**Result** ✓ Passed**MOT #4** 2014-10-25 09:16**MOT test number** 349748594285**Result** ✓ Passed

Advice Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #3 2013-10-25 10:54**MOT test number** 226618193226**Result** ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice N/s/r tyre has cut on side wall but not deep enough to reach cords

Notice N/s/f tyre has cut on side wall but not deep enough to reach cords

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2012-10-06 08:45**MOT test number** 958220582227**Result** ✓ Passed



MOT #1

2011-11-01 11:37

MOT test number

467035501359

Result

✓ Passed

- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice

Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice

Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
25 October 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	25 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 VK58VAJ
Plate since	2019-06-29
Current registration	 VK58VAJ
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-30
Last registration	2023-10-25
Complete history	See info



Registration #1	2008-09-30	7 mi
Registration #2	2011-11-01	32.526 mi
Registration #3	2012-10-06	41.661 mi
Registration #4	2013-10-25	50.557 mi
Registration #5	2014-10-25	58.332 mi
Registration #6	2015-10-24	63.653 mi
Registration #7	2016-10-22	68.831 mi
Registration #8	2017-10-28	71.210 mi
Registration #9	2018-06-11	72.981 mi
Registration #10	2019-06-20	75.277 mi
Registration #11	2019-06-20	75.277 mi
Registration #12	2019-06-20	75.277 mi
Registration #13	2019-06-20	75.277 mi
Registration #14	2019-06-20	75.277 mi
Registration #15	2019-06-20	75.277 mi
Registration #16	2019-06-20	75.277 mi
Registration #17	2019-06-20	75.277 mi
Registration #18	2019-06-20	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1300 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	26692030431803