



report date: 2024-03-29

General information

Make	MINI
Model	PACEMAN COOPER S
Colour	Grey
Year of manufacture	2014
Top speed	135 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	46.3 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 2

Date 2023-10-03

Pictures 9

Listing price [View report](#)



source: cargurus.co.uk

Entry 1

Date 2022-04-16

Pictures 15

Listing price [View report](#)



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-18
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	14
Total items failed	0

MOT #9	2024-03-19 13:28
MOT test number	394708690523
Result	✓ Passed
Next expiry date	2025-03-18
Minor	Front Windscreen damaged but not adversely affecting driver's view (chip stone). (3.2 (a) (i))

MOT #8	2023-08-29 11:50
MOT test number	874932042061
Result	✓ Passed
Minor	Front Windscreen damaged but not adversely affecting driver's view stonechip (3.2 (a) (i))

MOT #7	2022-09-03 09:06
MOT test number	387713778601
Result	✓ Passed

MOT #6	2021-08-23 13:52
MOT test number	229308602569
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2021-08-20 11:11**MOT test number** 834583784219**Result** ✗ Failed**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**DANGEROUS** Offside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))**MAJOR** Offside Rear Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2020-06-23 15:28**MOT test number** 668456313448**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #3** 2020-06-23 10:03**MOT test number** 496565060548**Result** ✗ Failed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2019-03-19 13:18**MOT test number** 162044145991**Result** ✓ Passed



MOT #1	2017-09-09 09:51
MOT test number	553356893432
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Under trays + engine bay covers fitted when tested



Tax & MOT check

X

Untaxed

Tax expired:
5 September 2023

✓

MOT

Expires:
18 March 2025

Tax status	Expired at 5 September
Days left	238 days too late
MOT expiry date	18 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-05
Last registration	2024-03-19
Complete history	See info



Registration #1	2014-09-05	28 mi
Registration #2	2017-09-09	16.694 mi
Registration #3	2019-03-19	23.249 mi
Registration #4	2020-06-23	28.190 mi
Registration #5	2020-06-23	28.192 mi
Registration #6	2021-08-20	41.586 mi
Registration #7	2022-03-20	55.277 mi
Registration #8	2022-03-20	55.277 mi
Registration #9	2022-03-20	55.277 mi
Registration #10	2022-03-20	55.277 mi
Registration #11	2022-03-20	55.277 mi
Registration #12	2024-03-19	55.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1522 mm
Length	4115 mm
Wheel base	2596 mm
Kerb weight	1305 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	A004J825