



report date: 2024-03-28

General information

Make	FORD
Model	KUGA LX TDCI
Colour	Silver
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H






Internet history

Entry 2

Date	2022-01-07
Pictures	16
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-05-25
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-18
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	32
Total items failed	8

MOT #20	2024-03-19 14:46
MOT test number	381979914401
Result	✓ Passed
Next expiry date	2025-03-18

MOT #19	2023-03-17 15:28
MOT test number	681793413185
Result	✓ Passed

MOT #18	2023-03-17 14:26
MOT test number	831233539274
Result	✗ Failed
MAJOR Road wheel fixing missing ax each wheel (5.2.1 (a) (i))	
MAJOR Rear Suspension arm pin or bush excessively worn n/s and o/s trailing arm bushes detached (5.3.4 (a) (i))	

MOT #17	2022-02-14 09:31
MOT test number	520446082803
Result	✓ Passed

MOT #16	2020-10-30 16:06
MOT test number	224178058793
Result	✓ Passed



MOT #15	2020-10-29 16:06
MOT test number	533889352189
Result	✗ Failed
MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #14	2019-10-21 10:01
MOT test number	646946119897
Result	✓ Passed

MOT #13	2018-10-18 13:01
MOT test number	900381340323
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Front Valve stem slightly damaged (5.2.3 (j))	
Advice Offside Front Valve stem slightly damaged (5.2.3 (j))	

**MOT #12** 2018-10-17 13:04**MOT test number** 922811436419**Result** ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))
- MAJOR** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Valve stem slightly damaged (5.2.3 (j))
- MAJOR** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Nearside Front Valve stem slightly damaged (5.2.3 (j))
- MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 235 50 r18 (5.2.3 (d) (i))

MOT #11 2017-10-20 13:30**MOT test number** 407137613330**Result** ✓ Passed

**MOT #10**

2017-10-19 13:04

MOT test number

870084688375

Result**✗ Failed**

- Advice** Nearside Front Steering system has slight free play detected at steering wheel inner rack end (2.2.A.1b)
- Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Engine malfunction light on
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Front Steering system has slight free play detected at steering wheel inner rack end (2.2.A.1b)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** O/s door mirror glass cracked

MOT #9

2016-03-31 14:07

MOT test number

626225198568

Result**✓ Passed**

- Advice** Offside Front Obligatory mirror obscured but not seriously affecting the rear view (8.1.2a)
- Advice** Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8

2016-03-24 13:25

MOT test number

651921901491

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Front wheel bearing rough when rotated (2.5.A.2)
- Advice** Offside Front Obligatory mirror obscured but not seriously affecting the rear view (8.1.2a)
- Advice** Rear Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Rear Body insecure and dangerous to other road users wheel arch (6.1.B.1b)

**MOT #7** 2015-04-01 16:04**MOT test number** 695501095031**Result** ✓ Passed**MOT #6** 2014-04-04 17:16**MOT test number** 349194994091**Result** ✓ Passed**MOT #5** 2014-04-04 12:33**MOT test number** 128304194062**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-11-12 12:35**MOT test number** 197747312393**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-11-12 11:49**MOT test number** 206467112364**Result** ✗ Failed**Fail** Nearside Side repeater not working (1.4.A.2c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2011-11-15 16:32
MOT test number	418469711418
Result	✓ Passed

MOT #1	2011-11-08 17:03
MOT test number	806272211379
Result	✗ Failed

Fail

Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
18 March 2025

Tax status	Valid until 1 August
Days left	95
MOT expiry date	18 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-11-24
Last registration	2024-03-19
Complete history	See info



Registration #1	2008-11-24	27 mi
Registration #2	2011-11-08	46.800 mi
Registration #3	2011-11-15	47.270 mi
Registration #4	2012-11-12	67.539 mi
Registration #5	2012-11-12	67.539 mi
Registration #6	2014-04-04	87.567 mi
Registration #7	2014-04-04	87.567 mi
Registration #8	2015-04-01	106.382 mi
Registration #9	2016-03-24	112.361 mi
Registration #10	2016-03-31	112.387 mi
Registration #11	2017-10-19	125.269 mi
Registration #12	2017-10-20	125.274 mi
Registration #13	2019-05-20	151.377 mi
Registration #14	2019-05-20	151.377 mi
Registration #15	2019-05-20	151.377 mi
Registration #16	2019-05-20	151.377 mi
Registration #17	2019-05-20	151.377 mi
Registration #18	2019-05-20	151.377 mi
Registration #19	2019-05-20	151.377 mi
Registration #20	2019-05-20	151.377 mi
Registration #21	2019-05-20	151.377 mi
Registration #22	2019-05-20	151.377 mi
Registration #23	2019-05-20	151.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	8R41969