



FP03SBX


report date: 2024-03-29

General information

Make	AUDI
Model	TT QUATTRO (180BHP)
Colour	Silver
Year of manufacture	2003
Top speed	140 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	180 BHP
Max. torque	235 Nm at 1.950 rpm
Engine capacity	1.781 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.7 mpg
Consumption extra urban	37.7 mpg
Consumption combined	30.1 mpg
CO2 emission	228 g/km
CO2 label	L







Internet history

Entry 8

Date 2021-12-26

Pictures 10

Listing price [View report](#)




source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 7

Date 2021-12-05

Pictures 10

Listing price [View report](#)




source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 6

Date 2021-10-03

Pictures 10

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 5

Date 2021-09-02


CarCheck.co.uk

Pictures

10

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 4

Date


2021-08-10

Pictures

10

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 3

Date


2021-07-21

Pictures

10

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date



2021-06-30

Pictures

10

Listing price



[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-06-09
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-01-09
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	22
Total items failed	13

MOT #20	2022-01-10 15:34
MOT test number	832037876534
Result	✓ Passed
Next expiry date	2023-01-09

MOT #19	2020-10-12 09:48
MOT test number	120334331798
Result	✓ Passed
Minor	Front Outer Drive shaft joint constant velocity boot severely deteriorated both (6.1.7 (g) (i))

MOT #18	2019-10-28 09:24
MOT test number	195450011039
Result	✓ Passed

MOT #17	2018-10-16 14:07
MOT test number	505195310874
Result	✓ Passed
Advice	Offside Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #16**

2017-10-25 15:25

MOT test number

402997054819

Result

✓ Passed

- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #15

2017-10-25 10:09

MOT test number

480993495054

Result

✗ Failed

- Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Offside Headlamp aim too low (1.8)
- Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Nearside Headlamp aim too high and too far to the right. (1.8)

MOT #14

2016-10-14 09:31

MOT test number

389433098155

Result

✓ Passed

- Advice** Offside Tyre worn close to the legal limit and nearside front (4.1.E.1)



MOT #13	2015-10-22 10:25
MOT test number	215249679867
Result	✓ Passed
Advice	Offside Rear nail in tyre

MOT #12	2015-10-20 11:21
MOT test number	830938856792
Result	✗ Failed
Advice	Offside Rear nail in tyre
Fail	Offside Headlamp aim too low (1.8)

MOT #11	2015-10-12 15:12
MOT test number	529912025304
Result	✗ Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Front brake disc in such a condition that it is seriously weakened (3.5.1i)
Advice	Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Fail	Body insecure and dangerous to other road users rear underneath cover (6.1.B.1b)

**MOT #10** 2014-10-16 16:33**MOT test number** 967969484211**Result** ✓ Passed**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Rear axle area is corroded**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2013-10-21 11:54**MOT test number** 587334793203**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2012-10-10 12:38**MOT test number** 439574582227**Result** ✓ Passed**MOT #7** 2011-07-18 16:03**MOT test number** 975699091157**Result** ✓ Passed**MOT #6** 2010-05-21 15:30**MOT test number** 143461940172**Result** ✓ Passed**MOT #5** 2009-05-27 14:29**MOT test number** 661557549198**Result** ✓ Passed



MOT #4	2008-05-07 16:27
MOT test number	260288428437
Result	✓ Passed
MOT #3	2007-05-18 12:23
MOT test number	591718037193
Result	✓ Passed
MOT #2	2007-05-16 16:13
MOT test number	264086137478
Result	✗ Failed
Fail	Nearside Track rod end ball joint has excessive play (2.2.B.1f)
Notice	Offside front tyre side wall damage
MOT #1	2006-05-02 12:59
MOT test number	800942326103
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
10 April 2021

✕
MOT

Expired:
9 January 2023

Tax status	Expired at 10 April 2021
Days left	1115 days too late
MOT expiry date	9 January 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2023-03-29
Current registration	XXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2003-05-01
Last registration	2022-01-10
Complete history	See info



Registration #1	2003-05-01	8 mi
Registration #2	2006-05-02	30.040 mi
Registration #3	2007-05-16	34.710 mi
Registration #4	2007-05-18	34.713 mi
Registration #5	2008-05-07	39.162 mi
Registration #6	2009-05-27	45.742 mi
Registration #7	2010-05-21	50.371 mi
Registration #8	2011-07-18	51.850 mi
Registration #9	2012-10-10	57.845 mi
Registration #10	2013-10-21	59.076 mi
Registration #11	2014-10-16	63.345 mi
Registration #12	2015-10-12	67.758 mi
Registration #13	2015-10-20	67.832 mi
Registration #14	2015-10-22	67.832 mi
Registration #15	2016-10-14	71.940 mi
Registration #16	2016-10-14	71.940 mi
Registration #17	2016-10-14	71.940 mi
Registration #18	2016-10-14	71.940 mi
Registration #19	2016-10-14	71.940 mi
Registration #20	2016-10-14	71.940 mi
Registration #21	2016-10-14	71.940 mi
Registration #22	2016-10-14	71.940 mi
Registration #23	2016-10-14	71.940 mi
Registration #24	2016-10-14	71.940 mi
Registration #25	2016-10-14	71.940 mi
Registration #26	2016-10-14	71.940 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1856 mm
Height	1345 mm
Length	4041 mm
Wheel base	2429 mm
Kerb weight	1465 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	ARY 014535