



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2013
Top speed	119 mph
Gearbox	6 speed automatic

Engine & fuel consumption


Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K



Internet history

Entry 1

Date	2021-10-23
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-27
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	34
Total items failed	10

MOT #14	2023-10-27 10:51
MOT test number	624985511395
Result	✓ Passed
Next expiry date	2024-10-27
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13**

2023-10-26 09:48

MOT test number

731912588943

Result**✗ Failed**

- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12

2022-10-21 08:48

MOT test number

731348207568

Result**✓ Passed**

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11

2021-10-28 13:00

MOT test number

623465038375

Result**✓ Passed**

- Advice** Both front tyres worn on inner edges

**MOT #10** 2020-12-12 14:19**MOT test number** 130671780243**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front oil leak on engine**MOT #9** 2019-11-17 14:07**MOT test number** 655614348611**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-11-12 11:39**MOT test number** 274848124077**Result** ✓ Passed**MOT #7** 2018-11-10 11:26**MOT test number** 988224942822**Result** ✗ Failed**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both rear bushes (5.3.4 (a) (i))**Advice** Oil leak**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear Brake pad(s) wearing thin Both (1.1.13 (a) (ii))**Advice** Small wear to both front brake discs

**MOT #6** 2017-12-11 16:32**MOT test number** 828046821458**Result** ✓ Passed**MOT #5** 2017-12-11 16:32**MOT test number** 875707807678**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #4** 2016-11-21 16:34**MOT test number** 153822843460**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2016-11-10 14:34**MOT test number** 714476099234**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Parking brake efficiency below requirements (3.7.E.1)

**MOT #2** 2016-01-15 09:32**MOT test number** 270561702512**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin outer (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin outer (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit 2mm inner edge (4.1.E.1)
- Advice** Offside Front Brake pad(s) wearing thin outer (3.5.1g)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1 2016-01-15 09:32**MOT test number** 822585034982**Result** ✗ Failed

- Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)
- Advice** Nearside Front Brake pad(s) wearing thin outer (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin outer (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit 2mm inner edge (4.1.E.1)
- Advice** Offside Front Brake pad(s) wearing thin outer (3.5.1g)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
27 October 2024

Tax status		Valid until 1 November
Days left		186
MOT expiry date		27 October 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 BV13FNC
Plate since	2019-06-29
Current registration	 BV13FNC
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-03-01
Last registration	2023-10-27
Complete history	See info



Registration #1	2013-03-01	28 mi
Registration #2	2016-01-15	20.346 mi
Registration #3	2016-01-15	20.346 mi
Registration #4	2016-11-10	28.088 mi
Registration #5	2016-11-21	28.391 mi
Registration #6	2017-12-11	30.037 mi
Registration #7	2017-12-11	30.037 mi
Registration #8	2018-11-10	34.637 mi
Registration #9	2019-05-29	35.377 mi
Registration #10	2019-05-29	35.377 mi
Registration #11	2019-05-29	35.377 mi
Registration #12	2019-05-29	35.377 mi
Registration #13	2019-05-29	35.377 mi
Registration #14	2019-05-29	35.377 mi
Registration #15	2019-05-29	35.377 mi
Registration #16	2019-05-29	35.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	222782K