



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Silver
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-27
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	19
Total items failed	12

MOT #19	2024-01-22 15:58
MOT test number	670448666412
Result	✓ Passed
Next expiry date	2025-01-27
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18	2024-01-22 12:42
MOT test number	980940888088
Result	✗ Failed
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #17** 2023-01-23 13:28**MOT test number** 681281302469**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Both (2.1.3 (g) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #16** 2022-01-21 14:15**MOT test number** 241138560859**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #15** 2021-01-28 16:05**MOT test number** 630844965508**Result** ✓ Passed**MOT #14** 2021-01-27 16:22**MOT test number** 158909564016**Result** ✗ Failed**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MOT #13** 2019-03-27 16:05**MOT test number** 226483101537**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12** 2019-03-25 09:35**MOT test number** 984199990833**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2018-03-23 16:05**MOT test number** 228721099389**Result** ✓ Passed**MOT #10** 2017-03-28 09:36**MOT test number** 322041284888**Result** ✓ Passed**MOT #9** 2016-03-03 16:08**MOT test number** 728234537416**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2016-03-02 15:01**MOT test number** 465912462357**Result** ✗ Failed

- Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)
- Fail** Nearside Rear rear brake recording little or no effort (3.7.B.5a)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Rear rear parking (secondary) brakes imbalanced (3.7.B.6b)
- Fail** Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #7 2015-03-10 14:41**MOT test number** 538069865079**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2014-03-11 13:33**MOT test number** 686680774099**Result** ✓ Passed**MOT #5** 2014-03-11 10:26**MOT test number** 827930474046**Result** ✗ Failed

- Fail** Rear Exhaust system not adequately supported (7.1.1)
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #4 2013-03-19 15:00**MOT test number** 505048273024**Result** ✓ Passed



MOT #3	2012-03-19 12:00
MOT test number	657509572019
Result	✓ Passed

MOT #2	2011-03-17 09:10
MOT test number	267546471057
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #1	2010-03-24 10:06
MOT test number	424763680062
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
27 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	27 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-31
Last registration	2024-01-22
Complete history	See info



Registration #1	2007-03-31	25 mi
Registration #2	2010-03-24	25.813 mi
Registration #3	2011-03-17	30.882 mi
Registration #4	2012-03-19	36.584 mi
Registration #5	2013-03-19	41.996 mi
Registration #6	2014-03-11	47.357 mi
Registration #7	2014-03-11	47.357 mi
Registration #8	2015-03-10	53.365 mi
Registration #9	2016-03-02	60.025 mi
Registration #10	2016-03-03	60.032 mi
Registration #11	2017-03-28	64.687 mi
Registration #12	2018-03-29	69.342 mi
Registration #13	2019-03-30	74.000 mi
Registration #14	2020-03-31	78.658 mi
Registration #15	2021-04-01	83.316 mi
Registration #16	2022-04-02	87.974 mi
Registration #17	2023-04-03	92.632 mi
Registration #18	2024-01-22	97.290 mi
Registration #19		
Registration #20		
Registration #21		
Registration #22		

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JB660199901