



PEUGEOT



MA56KLE


report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 VERVE E4
Colour	Black
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-04
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-05
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	38
Total items failed	31

MOT #21	2023-09-02 09:09
MOT test number	619205802759
Result	✓ Passed
Next expiry date	2024-09-05
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))

**MOT #20**

2023-08-30 16:30

**MOT test number**

256552803806

**Result****✗ Failed**

- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))
- Advice** Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Fail** Position lamp not working both front (4.2.1 (a) (ii))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Tyre tread depth below requirements of 1.6mm both front (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))

**MOT #19**

2022-08-24 14:16

**MOT test number**

736361690997

**Result****✓ Passed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing 185/65/r14 (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 175/65/r14 (5.2.3 (d) (ii))

**MOT #18**

2022-08-16 16:32

**MOT test number**

849190881844

**Result****✗ Failed**

- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing 185/65/r14 (5.2.3 (d) (ii))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Fuel tank insecure STRAP CORRODED (6.1.3 (a) (i))
- Advice** Central Exhaust has a minor leak of exhaust gases JOINT (6.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 175/65/r14 (5.2.3 (d) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Rear Spare wheel insecure in carrier (6.1.5 (b) (i))
- Fail** Offside Front Wheel bearing so rough it is likely to overheat or break up (5.1.3 (b) (ii))

**MOT #17**

2021-09-06 06:16

**MOT test number**

601669033749

**Result****✓ Passed****MOT #16**

2021-09-03 06:12

**MOT test number**

792261639351

**Result****✗ Failed**

- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Emissions not tested (8.2.1.2 (d))

**MOT #15**

2020-10-03 10:28

**MOT test number**

453038184141

**Result**

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2020-10-02 07:45

**MOT test number**

518268423324

**Result**

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #13**

2019-10-07 10:44

**MOT test number**

721165494436

**Result**

✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Items removed from driver's view prior to test**Advice** Backbox baffles collapsed inside**MOT #12**

2019-10-05 13:13

**MOT test number**

138333468322

**Result**

✗ Failed

**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Items removed from driver's view prior to test**Advice** Backbox baffles collapsed inside**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #11** 2018-10-01 13:55**MOT test number** 853173466108**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Items removed from driver's view prior to test**Minor** Rear Windscreen wiper blade defective (3.4 (b) (i))**MOT #10** 2017-09-29 11:07**MOT test number** 609950501724**Result** ✓ Passed**MOT #9** 2016-10-05 08:04**MOT test number** 136035320874**Result** ✓ Passed**MOT #8** 2015-10-01 09:41**MOT test number** 592874605572**Result** ✓ Passed**Advice** Rear exhaust brackets broken still supports system**MOT #7** 2015-09-28 10:11**MOT test number** 391433639375**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Rear exhaust brackets broken still supports system**Fail** Rear fog lamp not working (1.3.2b)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)



**MOT #6** 2014-10-03 09:17**MOT test number** 509236174270**Result** ✓ Passed**MOT #5** 2013-10-07 09:50**MOT test number** 469690083218**Result** ✓ Passed**MOT #4** 2012-10-08 12:24**MOT test number** 718702182279**Result** ✓ Passed**MOT #3** 2011-09-14 09:29**MOT test number** 846557751242**Result** ✓ Passed**MOT #2** 2010-09-17 15:18**MOT test number** 470740460268**Result** ✓ Passed**Notice** Bad oil leak on engine**MOT #1** 2009-09-23 15:25**MOT test number** 123086869290**Result** ✓ Passed**Advice** Front brake disc slightly scored (3.5.1h)**Advice** Offside Rear Rear wheel bearing has slight play (2.6.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
5 September 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	5 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>MA56KLE</b>
Plate since	2024-03-29
Current registration	<b>MA56KLE</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-29
Last registration	2023-09-02
Complete history	<a href="#">See info</a>



Registration #1	2006-09-29	24 mi
Registration #2	2009-09-23	22.750 mi
Registration #3	2010-09-17	28.569 mi
Registration #4	2011-09-14	33.170 mi
Registration #5	2012-10-08	36.509 mi
Registration #6	2013-10-07	41.907 mi
Registration #7	2014-10-03	45.126 mi
Registration #8	2015-09-28	48.964 mi
Registration #9	2015-10-01	49.045 mi
Registration #10	2016-10-05	52.749 mi
Registration #11	2017-09-29	56.238 mi
Registration #12	2018-10-01	60.008 mi
Registration #13	2019-09-29	63.777 mi
Registration #14	2020-09-29	67.546 mi
Registration #15	2021-09-29	71.315 mi
Registration #16	2022-09-29	75.084 mi
Registration #17	2023-09-02	78.853 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		
Registration #22		
Registration #23		

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	FST65298536