



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	JAZZ I-VTEC EX
Colour	White
Year of manufacture	2016
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	123 Nm at 5.000 rpm
Engine capacity	1.318 cc
Cylinders	4
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-11
Pictures	0
Listing price	<a href="#">View report</a>

source: yesauto.com



## MOT history

MOT expiry date	2025-03-30
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	16
Total items failed	3

MOT #8	2024-03-14 16:24
MOT test number	809026829714
Result	✓ Passed
Next expiry date	2025-03-30

MOT #7	2024-03-14 09:33
MOT test number	666595852356
Result	✗ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords deep cut on tread. (5.2.3 (d) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing extensive cracking on tread of tyre (5.2.3 (d) (ii))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge cut on outer sidewall of tyre. (5.2.3 (e))

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing extensive cracking on tread of tyre (5.2.3 (d) (ii))

**MOT #6** 2023-03-16 15:39**MOT test number** 144329544774**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Tyre slightly damaged/cracking or perishing Both rear tyres age cracking (5.2.3 (d) (ii))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords Cut in tread (5.2.3 (d) (i))

**MOT #5** 2023-03-16 15:39**MOT test number** 423037163021**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords Cut in tread (5.2.3 (d) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing Both rear tyres age cracking (5.2.3 (d) (ii))
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #4** 2022-03-21 15:44**MOT test number** 763938034829**Result** ✓ Passed**MOT #3** 2021-03-22 10:40**MOT test number** 690943573602**Result** ✓ Passed**MOT #2** 2020-03-23 11:48**MOT test number** 322328536817**Result** ✓ Passed



MOT #1	2019-03-27 11:05
MOT test number	752313377255
Result	✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
30 March 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	30 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-06-20
Current registration	 
Plate since	2019-06-20

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-03-31
Last registration	2024-03-14
Complete history	<a href="#">See info</a>



Registration #1	2016-03-31	13 mi
Registration #2	2019-03-27	12.356 mi
Registration #3	2020-03-23	14.914 mi
Registration #4	2021-03-22	15.869 mi
Registration #5	2022-03-20	16.777 mi
Registration #6	2023-03-20	17.685 mi
Registration #7	2024-03-14	18.593 mi
Registration #8		
Registration #9		
Registration #10		

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	85%
Pedestrian	73%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1694 mm
Height	1550 mm
Length	3995 mm
Wheel base	2530 mm
Kerb weight	1113 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L13B21014748