



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC 110
Colour	Silver
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-30
Pictures	3
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history****MOT #17**

2023-05-02 14:56

MOT test number

559621546050

Result**✗ Failed****Fail** Bumper damaged and likely to cause injury when grazed or contacted REAR (6.1.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))**Fail** Offside Rear Rear fog lamp does not emit a steady red light (4.5.4 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Registration plate lamp does not illuminate simultaneously with the position lamps NO NUMBER PLATE LIGHTS (4.7.2 (a))**Advice** TAIL GATE BADLY DAMAGED**MOT #16**

2022-04-08 15:21

MOT test number

793108061913

Result**✓ Passed****Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Sill (5.3.6 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Sill (5.3.6 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #15**

2022-04-08 11:02

MOT test number

720385641224

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Sill (5.3.6 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Sill (5.3.6 (a) (i))**Fail** Reversing lamp does not emit a steady white light (4.6.2 (a))**MOT #14**

2021-05-06 16:07

MOT test number

599491619717

Result**✓ Passed****Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

**MOT #13**

2020-04-21 13:48

MOT test number

742600758742

Result

✓ Passed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Front Suspension arm pin or bush worn but not resulting in excessive movement both rear bush (5.3.4 (a) (i))

MOT #12

2019-04-03 14:14

MOT test number

498418185442

Result

✓ Passed

Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rubber bush deteriorated (5.3.4 (a) (i))

Advice

Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Rear Inner Tyre worn close to legal limit/worn on edge 0mm (5.2.3 (e))

**MOT #11**

2019-04-02 09:01

MOT test number

837524078589

Result

✗ Failed

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge 0mm (5.2.3 (e))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rubber bush deteriorated (5.3.4 (a) (i))**MOT #10**

2018-04-04 13:53

MOT test number

134466948520

Result

✓ Passed

MOT #9

2017-04-03 08:20

MOT test number

148872984629

Result

✓ Passed

Advice Offside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit inner and outer edges worn (4.1.E.1)**Advice** Nearside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside Rear Nail in tyre**Advice** Offside rear tyre side wall cracked slightly

**MOT #8** 2017-03-31 09:59**MOT test number** 105064042264**Result** ✗ Failed**Advice** Nearside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside rear tyre side wall cracked slightly**Advice** Offside Rear Nail in tyre**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Advice** Offside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Tyre worn close to the legal limit inner and outer edges worn (4.1.E.1)**MOT #7** 2016-04-04 08:29**MOT test number** 137939525790**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-04-07 14:15**MOT test number** 868657995001**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #5** 2015-04-07 09:22**MOT test number** 239667095098**Result** ✗ Failed**Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Items removed from driver's view prior to test



MOT #4 2014-04-07 10:21

MOT test number 625277294013

Result ✓ Passed

MOT #3 2014-04-07 10:21

MOT test number 107347694052

Result ✗ Failed

Pass with rectification Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #2 2013-04-09 09:24

MOT test number 528159893035

Result ✓ Passed

MOT #1 2013-01-14 11:43

MOT test number 767724513091

Result ✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-02-19
Last registration	2023-05-02
Complete history	See info



Registration #1	2010-02-19	25 mi
Registration #2	2013-01-14	34.484 mi
Registration #3	2013-04-09	35.217 mi
Registration #4	2014-04-07	40.812 mi
Registration #5	2015-04-07	46.192 mi
Registration #6	2015-04-07	46.192 mi
Registration #7	2016-04-04	55.538 mi
Registration #8	2017-03-31	70.281 mi
Registration #9	2017-04-03	70.368 mi
Registration #10	2018-05-02	75.277 mi
Registration #11	2018-05-02	75.277 mi
Registration #12	2018-05-02	75.277 mi
Registration #13	2018-05-02	75.277 mi
Registration #14	2018-05-02	75.277 mi
Registration #15	2018-05-02	75.277 mi
Registration #16	2018-05-02	75.277 mi
Registration #17	2018-05-02	75.277 mi
Registration #18	2018-05-02	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AU23426