




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SWB WV 130TDI E4 TIP
Colour	Grey
Year of manufacture	2007
Gearbox	6 speed automatic

Engine & fuel consumption

Power	130 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
CO2 emission	251 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-05-23
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-08-17
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	38
Total items failed	20

MOT #19	2023-08-15 10:14
MOT test number	857302433270
Result	✓ Passed
Next expiry date	2024-08-17
Advice	Central exhaust corroded

MOT #18	2022-08-15 10:15
MOT test number	390796743891
Result	✓ Passed

MOT #17	2021-08-02 08:23
MOT test number	183147916006
Result	✓ Passed
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16	2021-07-26 09:00
MOT test number	550384104729
Result	✗ Failed
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

**MOT #15**

2020-08-18 13:49

**MOT test number**

291713240395

**Result**

✓ Passed

**Minor**

Offside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #14**

2020-08-12 13:00

**MOT test number**

250092197786

**Result**

✗ Failed

**Fail**

Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))

**Fail**

Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail**

Offside Front Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Fail**

Nearside Rear Headlamp aim too high (4.1.2 (a))

**Fail**

Offside Front Macpherson strut mounting likely to fail (5.3.3 (b) (ii))

**Minor**

Offside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13**

2019-04-18 16:58

**MOT test number**

699097445988

**Result**

✓ Passed

**Advice**

Hand brake lever cover missing

**Advice**

Anti-roll bar pin or bush worn but not resulting in excessive movement front centre d bushes (5.3.4 (a) (i))

**Advice**

Rear silencer box outer cover corroded

**Advice**

Hand brake warning light on switch insecure

**Advice**

Offside Front Shock absorbers has a slightly worn bush top strut top bearing starting to wear (5.3.2 (c))

**MOT #12**

2019-04-18 16:25

**MOT test number**

270416540472

**Result****✗ Failed****Advice**

Nearside Front steering inner knuckle joint starting to wear

**Advice**

Rear silencer box outer cover corroded

**Fail**

Driver's view of an obligatory external mirror materially affected by an obstruction centre objects (3.1 (a) (ii))

**Advice**

Anti-roll bar pin or bush worn but not resulting in excessive movement front centre d bushes (5.3.4 (a) (i))

**Advice**

Rear seats not in use

**Advice**

Hand brake lever cover missing

**Advice**

Hand brake warning light on switch insecure

**Advice**

Offside Front Shock absorbers has a slightly worn bush top strut top bearing starting to wear (5.3.2 (c))

**MOT #11**

2018-04-16 14:46

**MOT test number**

269772560343

**Result****✓ Passed****Advice**

Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Corrosion to exhaust system

**MOT #10**

2018-04-16 08:24

**MOT test number**

444988942796

**Result****✗ Failed****Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Corrosion to exhaust system**Fail** Nearside Headlamp not working on main beam (1.7.5a)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9**

2017-05-26 16:13

**MOT test number**

287025307396

**Result****✓ Passed****Advice** Items removed from driver's view prior to test**Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement  
Near and offside (2.4.G.2)**Advice** Offside Front Road tyre getting low**Advice** Oil leak**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Park brake covers missing**Advice** Front Wipers not very good at clearing screen

**MOT #8** 2017-05-26 10:59**MOT test number** 128522420196**Result** ✗ Failed**Fail** Offside Front position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)**Advice** Front Wipers not very good at clearing screen**Fail** Nearside Lower Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Items removed from driver's view prior to test**Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Near and offside (2.4.G.2)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Road tyre getting low**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Offside Lower Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Oil leak**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Park brake covers missing**MOT #7** 2016-05-12 13:21**MOT test number** 328629540980**Result** ✓ Passed**MOT #6** 2015-06-16 17:26**MOT test number** 386587265198**Result** ✓ Passed

**MOT #5** 2014-03-05 12:21**MOT test number** 458564164078**Result** ✓ Passed**MOT #4** 2012-03-28 16:39**MOT test number** 155708482480**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-03-28 09:52**MOT test number** 909418982039**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-03-25 10:02**MOT test number** 925024281090**Result** ✓ Passed**MOT #1** 2010-03-24 09:24**MOT test number** 530443480038**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
17 August 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	17 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>WV07ZNG</b>
Plate since	2019-09-29
Current registration	 <b>WV07ZNG</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-09
Last registration	2023-08-15
Complete history	<a href="#">See info</a>



Registration #1	2007-03-09	28 mi
Registration #2	2010-03-24	60.558 mi
Registration #3	2011-03-25	79.418 mi
Registration #4	2012-03-28	96.542 mi
Registration #5	2012-03-28	96.542 mi
Registration #6	2014-03-05	131.215 mi
Registration #7	2015-06-16	154.261 mi
Registration #8	2016-05-12	169.858 mi
Registration #9	2017-05-26	184.257 mi
Registration #10	2017-05-26	184.257 mi
Registration #11	2018-04-16	191.471 mi
Registration #12	2019-05-20	201.277 mi
Registration #13	2020-05-20	201.277 mi
Registration #14	2021-05-20	201.277 mi
Registration #15	2022-05-20	201.277 mi
Registration #16	2023-05-20	201.277 mi
Registration #17	2024-05-20	201.277 mi
Registration #18	2025-05-20	201.277 mi
Registration #19	2026-05-20	201.277 mi
Registration #20	2027-05-20	201.277 mi
Registration #21	2028-05-20	201.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	BNZ 040485