





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Black
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



## Internet history

### Entry 3

Date	2021-10-09

Pictures 10

Listing price <u>View report</u>









#### source: autoonline.co.uk

#### Entry 2


Date	2021-10-09
Pictures	0
Listing price	View report

### source: heycar.co.uk

#### Entry 1

Date	2021-10-08
Pictures	25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



# MOT history

MOT expiry date	2024-10-18
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	19
Total items failed	3

MOT #11	2023-10-19 09:37
MOT test number	181332008006
Result	<b>✓</b> Passed
Next expiry date	2024-10-18
Advice Nearside Front Tyre worn close to legal lin (5.2.3 (e))	nit/worn on edge worn on edge and 2mm 225/60/17
Minor Nearside Registration plate lamp inoperation (b) (i))	ve in the case of multiple lamps or light sources (4.7.1
Advice Nearside Rear Child Seat fitted not allowing	g full inspection of adult belt
Advice Offside Front Tyre worn close to legal limit (e))	/worn on edge worn on edge and 2mm 225/60/17 (5.2.3

MOT #10	2022-10-07 15:39
MOT test number	466753968510
Result	<b>✓</b> Passed
MOT #9	2021-10-19 11:16
MOT test number	479961962052
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



MOT test number

Fesult

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice O/s/f tyre is approaching limit

Advice O/s/r tyre tread getting low

Advice Rear brake pads looking low

N/s/r tyre is approaching limit

MOT test number

733008465046

Result

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



MOT #5 2019-03-08 10:57
MOT test number 936942538072

Result × Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #4** 2018-03-20 13:59

**MOT test number** 274923753675

Result \sqrt{Passed}

MOT #3 2018-03-20 11:33

**MOT test number** 272111656267

Result X Failed

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #2 2017-03-04 10:39

MOT test number 142854666349

Result \( \sqrt{Passed} \)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #1** 2017-03-03 12:45

MOT test number 156094607316

Result X Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Brake pad(s) wearing thin all brake pads (3.5.1g)

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	18 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
***************************************	
THE PARTY OF THE P	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-03-31
Last registration	2023-10-19
Complete history	See info



Registration #1	2014-03-31	15 mi
Registration #2	2017-03-03	41.109 mi
Registration #3	2017-03-04	41.110 mi
Registration #4	2018-03-20	54.530 mi
Registration #5	2018-03-20	54.530 mi
Registration #6	2019-03-08	65.484 mi
Registration #7	2019-03-08	65.485 mi
Registration #8	2020-03-06	76.465 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		D.277 es

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

# Additional information

Fuel tank capacity	58 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	age 12/12

Number of axles 2

**Engine number** D4FDEZ258681