





report date: 2024-03-29

General information

Make	MINI
Model	COOPER D ONE D
Colour	Silver
Year of manufacture	2013
Top speed	114 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



Internet history


Entry 1


Date 2022-03-04

Pictures 22

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-28
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	13
Total items failed	3

MOT #10	2024-02-27 16:03
MOT test number	639684909734
Result	✓ Passed
Next expiry date	2025-02-28
Advice Rear heat sheild loose	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #9	2024-02-27 10:33
MOT test number	396453210674
Result	X Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Rear heat sheild loose	
Minor Nearside Upper Stop lamp(s) with a multiple light source up to 1/2	not functioning (4.3.1 (a) (i))
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Minor Offside Registration plate lamp inoperative in the case of multiple I (i))	amps or light sources (4.7.1 (b)

CarCheck.co.uk page 3/12



MOT #8 2023-02-17 10:25

MOT test number 171644722396

Result ✓ Passed

Minor Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7 2022-03-01 14:27

MOT test number 884705939210

Result
✓ Passed

Advice Rear Discs worn and pitted

MOT #6 2021-07-20 10:27

MOT test number 998080662396

MOT #5 2020-07-22 15:09

MOT test number 910725893679

Result ✓ Passed

MOT #4 2019-05-13 12:51

MOT test number 502964282857

Result \(\sqrt{Passed} \)

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #3 2018-04-27 09:23

MOT test number 867391726924

Result
✓ Passed

CarCheck.co.uk page 4/12



MOT #2 2017-05-26 11:18

MOT test number 256649529206

MOT #1 2016-06-16 11:10

MOT test number 510379100770

Advice Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	28 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
HARMAN CO.	

HARMAN AND AND AND AND AND AND AND AND AND A	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Europeat regulatration	NK UK
	UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-07-11
Last registration	2024-02-27
Complete history	See info



Registration #1	2013-07-11	13 mi
Registration #2	2016-06-16	39.399 mi
Registration #3	2017-05-26	60.464 mi
Registration #4	2018-04-27	77.984 mi
Registration #5	2019-05-13	91.228 mi
Registration #6	2020-07-22	112.385 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		77.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 I	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	4 page 1	2/12

Number of axles 2

Engine number 70728575