





report date: 2024-03-29

General information

Make	VAUXHALL
Model	MERIVA EXCLUSIV AC CDTI ECOFLEX S/S
Colour	Red
Year of manufacture	2014
Top speed	122 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-31

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2024-08-02
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #8	2023-07-25 12:59
MOT test number	886893932686
Result	✓ Passed
Next expiry date	2024-08-02

MOT #7		2022-07-30 10:10
MOT test	number	805934257065
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Central Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1-	4 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #6	2021-08-03 07:34
MOT test number	152183647359
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

× Failed

MOT #5 2020-09-10 09:55

MOT test number 298321222113

MOT #4 2019-09-09 09:41

MOT test number 418552421822

Result J Passed

Advice Nearside Rear Outer Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #3 2018-09-10 14:01

MOT test number 244229436103

Result \rightarrow Passed

Advice Oil leak, but not excessive gearbox area (8.4.1 (a) (i))

MOT #2 2018-09-10 10:31

MOT test number 564896345626

Fail Nearside Front Headlamp aim too high (4.1.2 (a))

Result

Advice Oil leak, but not excessive gearbox area (8.4.1 (a) (i))

MOT #1 2017-08-28 14:41

MOT test number 836364536493

Result
✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29


Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	

Damage 2	
Date	
Category	



Extra VAUXHALL salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlonere.	

	More info >
Plate changes See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK SIE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
011.1.6.	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-09-12
Last registration	2023-07-25
Complete history	See info



Registration #1	2014-09-12	9 mi
Registration #2	2017-08-28	7.572 mi
Registration #3	2018-09-10	12.295 mi
Registration #4	2018-09-10	12.295 mi
Registration #5	2019-09-09	16.952 mi
Registration #6		77,777 44
Registration #6 Registration #7		11.77 es
-		11.777 es
Registration #7		11,777 est 11,777 est 11,777 est

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1518 kg
Max. allowed weight	2040 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	A1141184FWXX0075LVL

CarCheck.co.uk page 11/11