





General information

| Make | CITROEN |
|---------------------|-------------------|
| Model | C1 PURETECH FLAIR |
| Colour | Red |
| Year of manufacture | 2017 |
| Top speed | 106 mph |
| 0 - 60 mph | 11.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption


| Power | 82 BHP |
|-------------------------|---------------------|
| Max. torque | 116 Nm at 2.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 52.3 mpg |
| Consumption extra urban | 76.4 mpg |
| Consumption combined | 65.7 mpg |
| CO2 emission | 99 g/km |
| CO2 label | A |







| Internet history | |
|------------------------|-------------|
| Entry 4 | |
| Date | 2023-06-14 |
| Pictures | 0 |
| Listing price | View report |
| source: carcraft.co.uk | |
| Entry 3 Date | 2023-03-22 |
| Pictures | 0 |
| Listing price | View report |
| source: carcraft.co.uk | |
| Entry 2 Date | 2023-03-17 |
| Pictures | 13 |
| Listing price | View report |
| | |



source: cargurus.co.uk

| Entry 1 | |
|---------------|-------------|
| Date | 2021-08-20 |
| Pictures | 12 |
| Listing price | View report |
| | |



source: cargurus.co.uk









MOT history

| MOT expiry date | 2024-11-06 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 5 |
| Failed MOT tests | 0 |
| Total advice items | 12 |
| Total items failed | 0 |

| MOT #5 | 2023-11-07 08:45 |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| MOT test number | 476647276399 |
| Result | Passed |
| Next expiry date | 2024-11-06 |
| AdviceFront Brake disc worn, pitted or scored, but not seriously weakened Both fr corroding. (1.1.14 (a) (ii))AdviceFront Exhaust mounting defective Front exhaust rubber mount splitting. (6. | |

| MOT #4 | | 2023-01-26 10:15 |
|----------|----------------------------------------------------------------------------------|------------------|
| MOT test | number | 534297477022 |
| Result | | ✓ Passed |
| Advice | Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Front Exhaust mounting defective Front exhaust pipe rubber mount splitting. (6.1 | .2 (a)) |





| MOT #3 | | 2022-01-31 14:13 |
|----------|-----------------------------------------------------------------------------|------------------|
| MOT test | number | 254947941144 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #2 | 2021-09-08 13:50 |
|-----------------|------------------|
| MOT test number | 593072925242 |
| Result | ✓ Passed |

| MOT #1 | 2020-09-01 10:41 |
|------------------------------------------------------------------------------|------------------|
| MOT test number | 594222591128 |
| Result | ✓ Passed |
| Advice Front tyres perished | |
| Advice Front wiper split at ends | |
| Minor Offside Obligatory mirror slightly damaged glass cracked (3.3 (b) (i)) | |



Tax & MOT check

| Taxed Tax due: 1 November 2024 | ✓ MOT Expires: 6 November 2024 |
|----------------------------------------------------|-----------------------------------------|
| Tax status | Valid until 1 November |
| Days left | 187 |
| MOT expiry date | 6 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | E |
| First licence fee (12 months) | £ 165,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | · · · |
| Category | AMPL |
| Туре | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|----------------------------------------------------------------|-------------|
| ********** | |
| ******* | |
| ****** | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |

More info \rightarrow





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Mileage registrations10First mileage registration2017-09-20Last registration2023-11-07Complete historySee info |
|----------------------------------------------------------------------------------------------------------------|
| Last registration2023-11-07 |
| - |
| Complete history See info |
| |



| Registration #1 | 2017-09-20 | 16 mi |
|------------------|------------|------------|
| Registration #2 | 2020-09-01 | 10.784 mi |
| Registration #3 | | 11.177 mi |
| Registration #4 | 2021-09-08 | 14.012 mi |
| Registration #5 | 2022-01-31 | 14.046 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 esi |
| Registration #10 | | 10.377 mi |

More info >





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 68% |
| Children | 73% |
| Pedestrian | 53% |
| Safety systems | 71% |
| Overall rating | 66% |
| Video | see crash video |



| Dimensions & weight | |
|--------------------------------------------------------|-------------------------------|
| Width | 1615 mm |
| Height | 1460 mm |
| Length | 3465 mm |
| Wheel base | 2340 mm |
| Kerb weight | 865 kg |
| Max. allowed weight | 1240 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 35 I |
| | 35 l Multi-Point Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Multi-Point Injection |
| Fuel tank capacity Fuel delivery Number of doors | Multi-Point Injection 5 |