



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Silver
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 2

Date	2023-06-21
Pictures	33
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-09-02
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-05
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	35
Total items failed	10

MOT #17	2023-12-06 17:05
MOT test number	403270086602
Result	✓ Passed
Next expiry date	2024-12-05
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #16**

2023-11-25 09:39

MOT test number

557407341958

Result**✗ Failed****Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Front Upper Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Upper Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #15**

2022-11-10 14:10

MOT test number

215807408610

Result**✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14**

2022-11-10 14:10

MOT test number

876613870620

Result**✗ Failed****Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2021-10-18 12:23

MOT test number

401236367969

Result

✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12**

2021-10-18 10:26

MOT test number

516250823691

Result

✗ Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11**

2021-03-31 10:10

MOT test number

431994070324

Result

✓ Passed

Advice Engine bay covers and under body trays**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Items removed from driver's view prior to test**Advice** Nearside Front tyre tread low on edge**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #10** 2020-03-28 12:25**MOT test number** 133955456526**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2018-04-03 14:09**MOT test number** 154393222498**Result** ✓ Passed**MOT #8** 2017-04-11 11:26**MOT test number** 397552623895**Result** ✓ Passed**Advice** Offside Front Outer Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre perished.**MOT #7** 2016-02-03 11:43**MOT test number** 654137909042**Result** ✓ Passed**Advice** Front brake pads getting low**Advice** Front tyres wearing on inside and outside and getting v/low**Advice** Engine covers and under trays fitted**MOT #6** 2015-01-21 13:59**MOT test number** 429121425051**Result** ✓ Passed**Notice** Both front tyres wearing low on edges

**MOT #5** 2014-01-21 13:05**MOT test number** 408301324083**Result** ✓ Passed**Notice** Front brake discs slightly worn**MOT #4** 2013-01-22 09:47**MOT test number** 207202023064**Result** ✓ Passed**MOT #3** 2012-01-23 09:30**MOT test number** 105803522457**Result** ✓ Passed**MOT #2** 2011-01-21 16:20**MOT test number** 275551521032**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-01-21 16:20**MOT test number** 185591121427**Result** ✗ Failed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
5 December 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	5 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2024-03-29
Current registration	 XXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-01-25
Last registration	2023-12-06
Complete history	See info



Registration #1	2008-01-25	21 mi
Registration #2	2011-01-21	15.341 mi
Registration #3	2012-01-23	25.149 mi
Registration #4	2013-01-22	32.096 mi
Registration #5	2014-01-21	42.413 mi
Registration #6	2015-01-21	51.407 mi
Registration #7	2016-02-03	59.664 mi
Registration #8	2017-04-11	68.880 mi
Registration #9	2018-04-03	74.498 mi
Registration #10	2020-03-28	82.142 mi
Registration #11	2020-03-28	82.142 mi
Registration #12	2020-03-28	82.142 mi
Registration #13	2020-03-28	82.142 mi
Registration #14	2020-03-28	82.142 mi
Registration #15	2020-03-28	82.142 mi
Registration #16	2020-03-28	82.142 mi
Registration #17	2020-03-28	82.142 mi
Registration #18	2020-03-28	82.142 mi
Registration #19	2020-03-28	82.142 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1721 mm
Height	1502 mm
Length	4129 mm
Wheel base	2516 mm
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number

BFS 071176