



report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER COOPER
Colour	Black
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	149 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	52.3 mpg
Consumption combined	41.5 mpg



LABEL UNKNOWN

**MOT history**

MOT #19	2020-01-09 12:51
MOT test number	453940476466
Result	✓ Passed
Next expiry date	2021-01-18
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Play in steering rack inner joint(s)

MOT #18	2020-01-07 15:11
MOT test number	600185205409
Result	✗ Failed
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Front Play in steering rack inner joint(s)
MAJOR	Offside Front Direction indicator incorrect colour (4.4.3 (a))
MAJOR	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice	Nearside Front Play in steering rack inner joint(s)
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #17	2019-01-19 15:50
MOT test number	952397662153
Result	✓ Passed

MOT #16	2019-01-19 15:50
MOT test number	385396883108
Result	✗ Failed
<div>Pass with rectification</div> Nearside Front Direction indicator incorrect colour (4.4.3 (a))	

MOT #15	2017-12-16 10:26
MOT test number	639786755303
Result	✓ Passed
<div>Advice</div> Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)	
<div>Advice</div> Nearside Front Direction indicator slightly discoloured (1.4.A.2f)	
<div>Advice</div> Front Exhaust has a minor leak of exhaust gases (7.1.2)	
<div>Advice</div> Steering system slightly tight (2.2.D.1)	
<div>Advice</div> Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)	
<div>Advice</div> Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
<div>Advice</div> Parking brake lever has little reserve travel (3.1.6b)	

**MOT #14** 2016-12-22 15:50**MOT test number** 330587867742**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Steering system slightly tight (2.2.D.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #13 2015-11-19 12:55**MOT test number** 499086155241**Result** ✓ Passed

- Advice** Nearside Direction indicator slightly discoloured (1.4.A.2f)

MOT #12 2015-11-18 15:56**MOT test number** 693897184357**Result** ✗ Failed

- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Nearside Direction indicator slightly discoloured (1.4.A.2f)
- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #11** 2014-10-07 11:32**MOT test number** 279090084274**Result** ✓ Passed**Notice** O/side rear tyre tread cracked (border line pass)**Notice** N/side rear tyre tread cracking started**MOT #10** 2014-10-07 11:32**MOT test number** 818430484291**Result** ✗ Failed**Notice** O/side rear tyre tread cracked (border line pass)**Notice** N/side rear tyre tread cracking started**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #9** 2013-09-17 15:48**MOT test number** 208210863284**Result** ✓ Passed**MOT #8** 2012-09-28 14:11**MOT test number** 349702372256**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #7** 2012-09-28 13:38**MOT test number** 389452272213**Result** ✗ Failed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #6** 2011-10-03 13:36**MOT test number** 458616271286**Result** ✓ Passed**MOT #5** 2011-04-19 15:07**MOT test number** 537219701133**Result** ✓ Passed**MOT #4** 2010-04-09 12:05**MOT test number** 221109890039**Result** ✓ Passed**MOT #3** 2009-01-20 17:34**MOT test number** 511670529002**Result** ✓ Passed



MOT #2	2008-07-24 11:54
MOT test number	481826908248
Result	✓ Passed
Advice	Offside Rear rear brake grabbing slightly (3.7.A.5b)

MOT #1	2007-07-31 08:06
MOT test number	203402117282
Result	✓ Passed
Notice	Oil leak from the back of the engine
Advice	Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Notice	O/S/F Engine mounting loosing oil and getting weak
Advice	Tyre worn close to the legal limit (4.1.E.1)
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YL04ULU
Plate since	2019-09-28
Current registration	YL04ULU
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-07-16
Last registration	2020-01-09
Complete history	See info



Registration #1	2004-07-16	19 mi
Registration #2	2007-07-31	25.032 mi
Registration #3	2008-07-24	40.984 mi
Registration #4	2009-01-20	43.988 mi
Registration #5	2010-04-09	53.853 mi
Registration #6	2011-04-19	59.295 mi
Registration #7	2011-10-03	62.389 mi
Registration #8	2012-09-28	67.200 mi
Registration #9	2012-09-28	67.201 mi
Registration #10	2013-09-17	71.659 mi
Registration #11	2014-05-20	75.277 mi
Registration #12	2015-05-20	75.277 mi
Registration #13	2016-05-20	75.277 mi
Registration #14	2017-05-20	75.277 mi
Registration #15	2018-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2020-05-20	75.277 mi
Registration #18	2021-05-20	75.277 mi
Registration #19	2022-05-20	75.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1688 mm
Height	1408 mm
Length	3626 mm
Wheel base	2467 mm
Kerb weight	1125 kg
Max. allowed weight	1505 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	D133S198