





report date: 2024-03-28

General information

Make	PEUGEOT
Model	EXPERT E7 TAXI
Colour	Silver
Year of manufacture	2006
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	40.4 mpg
CO2 emission	186 g/km
CO2 label	I



CarCheck.co.uk page 1/11



report date: 2024-03-28


Internet history

Entry 1

Date 2021-08-28

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



SA56XUS report date: 2024-03-28

MOT history

MOT expiry date	2022-04-05
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	17
Total items failed	0

MOT #7	2021-04-06 10:21
MOT test number	725760280834
Result	✓ Passed
Next expiry date	2022-04-05
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front steering rack gaiter twisted	

MOT #6	2020-10-02 10:13
MOT test number	214890422525
Result	✓ Passed
Advice Brake pedal wearing smooth (1.1.2 (c)) Advice Nearside Front wishbone bush starting to wear/slight play	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #5 2020-09-29 10:03

MOT test number 276448481064

Result X Failed

MAJOR Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting outer sill corroded by patched area (6.2.2 (d) (i))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Offside Front steering rack boot outer clip insecure

Advice Brake pedal wearing smooth (1.1.2 (c))

Advice Nearside Front wishbone bush starting to wear/slight play

MOT #4 2020-07-10 11:21

MOT test number 185825567942

Minor Nearside Front Brake hose slightly damaged (1.1.12 (b) (i))

MOT #3 2020-07-07 15:02

MOT test number 242980433546

Result X Failed

DANGEROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Minor Nearside Front Brake hose slightly damaged (1.1.12 (b) (i))

Advice Parking brake failed during testing, possibly lever cable snapped.

MAJOR Main beam tell-tale not working (4.9.1 (a) (ii))

MOT #2 2019-10-07 07:06

MOT test number 804997223185

Result \rightarrow Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT test number

Failed

MAJOR

Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))

Advice

Offside Front dipped beam goes off when main beam switched on.

MAJOR

Offside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))

CarCheck.co.uk page 5/11



report date: 2024-03-28

Tax & MOT check

Tax expired: 26 July 2021



X MOT

Expired: 5 April 2022

Tax status	Expired at 26 July 2021
Days left	1008 days too late
MOT expiry date	5 April 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/11



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this PEUGEOT had different number plates. about of pliates faste since

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2006-11-10
Last registration	2021-04-06
Complete history	See info



Registration #1	2006-11-10	11 mi
Registration #2	2019-10-04	177.710 mi
Registration #3	2019-10-07	177.724 mi
Registration #4	2020-07-07	352.437 mi
Registration #5	2020-07-10	352.495 mi
Registration #6		0.00 44
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 no

More info >

CarCheck.co.uk page 10/11



SA56XUS report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1927 mm
Length	4440 mm
Max. allowed weight	2505 kg

Additional information

Number of seats	8
Number of axles	2
Engine number	DYSX4024205

CarCheck.co.uk page 11/11