



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	CIVIC VTEC SE
Colour	Black
Year of manufacture	2018
Top speed	126 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	200 Nm at 4.500 rpm
Engine capacity	988 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	58.9 mpg
CO2 emission	110 g/km
CO2 label	B








Internet history

Entry 2



Date	2021-08-07
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-07
Pictures	19
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-09-14
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	7
Total items failed	7

MOT #6	2023-09-04 09:48
MOT test number	484583223762
Result	✓ Passed
Next expiry date	2024-09-14
Advice	Under tray fitted
Advice	Nearside Rear Nail in tyre

MOT #5	2023-09-04 07:39
MOT test number	956698383663
Result	✗ Failed
Advice	Nearside Rear Nail in tyre
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
Advice	Under tray fitted

MOT #4	2022-08-30 07:42
MOT test number	755828621785
Result	✓ Passed
Advice	Under tray fitted



MOT #3	2021-09-15 16:57
MOT test number	681323278729
Result	✓ Passed

MOT #2	2021-09-14 14:37
MOT test number	985169173328
Result	✗ Failed

- Fail** Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.5 (b) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Fail** Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #1	2021-03-29 10:32
MOT test number	592140477427
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
14 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	14 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	ML18WHX
Plate since	2019-03-28
Current registration	ML18WHX
Plate since	2019-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-03-29
Last registration	2023-09-04
Complete history	See info



Registration #1	2018-03-29	19 mi
Registration #2	2021-03-29	20.476 mi
Registration #3	2020-09-29	20.277 mi
Registration #4	2020-09-29	20.277 mi
Registration #5	2021-09-14	24.502 mi
Registration #6	2020-09-29	20.277 mi
Registration #7	2020-09-29	20.277 mi
Registration #8	2020-09-29	20.277 mi
Registration #9	2020-09-29	20.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	75%
Pedestrian	75%
Safety systems	88%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1799 mm
Height	1434 mm
Length	4518 mm
Wheel base	2697 mm
Kerb weight	1348 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	P10A21018658