



A006WFE

report date: 2024-03-28

General information

Make	JAGUAR
Model	XJR V8 SUPER
Colour	Blue
Year of manufacture	2006
Top speed	155 mph
0 - 60 mph	5.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	400 BHP
Max. torque	552 Nm at 3.500 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.2 mpg
Consumption extra urban	31.4 mpg
Consumption combined	22.3 mpg
CO2 emission	289 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-11-02
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-19
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	40
Total items failed	14

MOT #17	2023-12-19 16:08
MOT test number	935426862308
Result	✓ Passed
Next expiry date	2024-12-19
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #16**

2023-10-17 12:20

MOT test number

154755277823

Result**✗ Failed**

- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Rear Outer Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Rear Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Rear Outer Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Nearside Front Brake pipe excessively corroded both pipes (1.1.11 (c))
- Fail** Nearside Rear Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Rear Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #15** 2022-12-08 09:38**MOT test number** 488883959664**Result** ✓ Passed**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases silencer (6.1.2 (a))**Advice** Nearside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Exhaust has a minor leak of exhaust gases silencer (6.1.2 (a))**Advice** Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #14** 2021-12-20 17:59**MOT test number** 989632408106**Result** ✓ Passed**MOT #13** 2020-12-17 14:56**MOT test number** 150644994244**Result** ✓ Passed**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #12** 2019-11-20 10:10**MOT test number** 215309028042**Result** ✓ Passed**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #11** 2018-11-14 11:38**MOT test number** 813557978869**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material There are 3 pipes slightly corroded (1.1.11 (c))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #10** 2017-11-25 14:34**MOT test number** 761864500830**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened corroded inner face (3.5.1i)**Advice** Offside Front front brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened corroded inner face (3.5.1i)**Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)**MOT #9** 2016-11-24 10:02**MOT test number** 724626539152**Result** ✓ Passed**MOT #8** 2015-10-21 10:44**MOT test number** 148792535655**Result** ✓ Passed

**MOT #7** 2014-07-14 15:15**MOT test number** 858155594167**Result** ✓ Passed**MOT #6** 2013-06-13 10:20**MOT test number** 808304363153**Result** ✓ Passed**Notice** Both front tyres wearing on edges**MOT #5** 2012-06-14 10:33**MOT test number** 236186362120**Result** ✓ Passed**Notice** Both front tyres wearing on edges**Notice** Off side rear outter door handle broken**MOT #4** 2011-06-10 16:55**MOT test number** 459411061139**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Off side rear door won,t open from out side**MOT #3** 2010-05-17 11:46**MOT test number** 114967930127**Result** ✓ Passed**Advice** Inner Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #2	2009-05-13 14:46
MOT test number	201533139133
Result	✓ Passed
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Small stone chips in windscreen

MOT #1	2009-05-13 09:29
MOT test number	353343839122
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Small stone chips in windscreen
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
19 December 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-28
Current registration	*****
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-05-24
Last registration	2023-12-19
Complete history	See info



Registration #1	2006-05-24	16 mi
Registration #2	2009-05-13	35.063 mi
Registration #3	2009-05-13	35.063 mi
Registration #4	2010-05-17	44.079 mi
Registration #5	2011-06-10	49.589 mi
Registration #6	2012-06-14	54.102 mi
Registration #7	2013-06-13	60.133 mi
Registration #8	2014-07-14	65.193 mi
Registration #9	2015-10-21	70.620 mi
Registration #10	2016-11-24	74.382 mi
Registration #11	2016-11-24	74.382 mi
Registration #12	2016-11-24	74.382 mi
Registration #13	2016-11-24	74.382 mi
Registration #14	2016-11-24	74.382 mi
Registration #15	2016-11-24	74.382 mi
Registration #16	2016-11-24	74.382 mi
Registration #17	2016-11-24	74.382 mi
Registration #18	2016-11-24	74.382 mi
Registration #19	2016-11-24	74.382 mi

More info >



Dimensions & weight

Width	2108 mm
Height	1448 mm
Length	5090 mm
Wheel base	3034 mm
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0510130954TG