



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Silver
Year of manufacture	2009
Top speed	106 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	79 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg
CO2 emission	142 g/km
CO2 label	F





Internet history

Entry 2

Date	2023-09-05
Pictures	11
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2022-08-05
Pictures	26
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2022-11-26
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	25
Total items failed	12

MOT #15 2021-11-27 13:28

MOT test number 323115669927

Result ✓ Passed

Next expiry date 2022-11-26

**Advice** Tyre slightly damaged/cracking or perishing all four (5.2.3 (d) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2021-11-23 11:55

MOT test number 669763289194

Result ✗ Failed

**Advice** Tyre slightly damaged/cracking or perishing all four (5.2.3 (d) (ii))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

**MOT #13**

2020-11-19 16:58

**MOT test number**

310990869823

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #12**

2020-11-04 12:24

**MOT test number**

813580974359

**Result**

✗ Failed

**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Windscreen wiper does not clear the windscreen effectively 22" (3.4 (b) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**MOT #11**

2019-05-04 10:49

**MOT test number**

683554544859

**Result**

✓ Passed

**Advice** Front bumper has slight damage/has been taped**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside front Macpherson strut has slight movement at the upper attachment

**MOT #10** 2019-05-04 08:19**MOT test number** 926679202612**Result** ✗ Failed

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front bumper has slight damage/has been taped
- Advice** Offside front Macpherson strut has slight movement at the upper attachment
- Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Both front brake discs worn, but not excessively
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #9** 2018-04-19 14:52**MOT test number** 114352863980**Result** ✓ Passed

- Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Inner Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2017-04-19 11:42**MOT test number** 977193284127**Result** ✓ Passed

**MOT #7** 2016-04-14 08:46**MOT test number** 773827012713**Result** ✓ Passed**Advice** Nearside Rear tyre has slight cracking**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Offside Rear tyre has slight cracking**MOT #6** 2015-04-23 13:06**MOT test number** 477153015180**Result** ✓ Passed**MOT #5** 2015-04-23 13:06**MOT test number** 215573615140**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2014-04-22 13:08**MOT test number** 416782414120**Result** ✓ Passed**MOT #3** 2013-03-11 12:27**MOT test number** 169690173004**Result** ✓ Passed**MOT #2** 2011-11-29 10:44**MOT test number** 548673031331**Result** ✓ Passed



MOT #1	2011-11-29 10:44
MOT test number	396893331344
Result	✗ Failed
Pass with rectification	Rear fog lamp not working (1.3.2b)
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✕  
**Untaxed**

**Tax expired:**  
10 July 2022

✕  
**MOT**

**Expired:**  
26 November 2022

<b>Tax status</b>	Expired at 10 July 2022
<b>Days left</b>	660 days too late
<b>MOT expiry date</b>	26 November 2022
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-01-09
Last registration	2021-11-27
Complete history	<a href="#">See info</a>



Registration #1	2009-01-09	13 mi
Registration #2	2011-11-29	13.060 mi
Registration #3	2013-03-11	16.388 mi
Registration #4	2014-04-22	20.029 mi
Registration #5	2015-04-23	22.844 mi
Registration #6	2016-04-14	23.871 mi
Registration #7	2017-04-19	25.542 mi
Registration #8	2018-04-19	26.306 mi
Registration #9	2019-05-20	26.306 mi
Registration #10	2019-05-20	26.306 mi
Registration #11	2019-05-20	26.306 mi
Registration #12	2019-05-20	26.306 mi
Registration #13	2019-05-20	26.306 mi
Registration #14	2019-05-20	26.306 mi
Registration #15	2019-05-20	26.306 mi
Registration #16	2019-05-20	26.306 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1040 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	1150820