




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SWB W/V 104TDI
Colour	Blue
Year of manufacture	2004
Top speed	99 mph
0 - 60 mph	18.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 2.000 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	36.7 mpg
CO2 emission	203 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-04
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-01-10
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	36
Total items failed	31

MOT #23	2024-01-10 10:28
MOT test number	659989532154
Result	✓ Passed
Next expiry date	2025-01-10

MOT #22	2023-01-10 12:48
MOT test number	921871715931
Result	✓ Passed
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #21	2023-01-10 09:55
MOT test number	964303387869
Result	✗ Failed
Fail	Service brake efficiency below requirements (1.2.2 (a) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #20	2022-01-11 17:20
MOT test number	375997205777
Result	✓ Passed

**MOT #19** 2020-12-09 13:39**MOT test number** 743039619958**Result** ✓ Passed**MOT #18** 2019-05-22 10:32**MOT test number** 573044092778**Result** ✓ Passed**MOT #17** 2018-04-04 10:55**MOT test number** 221820015209**Result** ✓ Passed**MOT #16** 2018-04-04 10:55**MOT test number** 343173599853**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #15** 2016-03-31 11:34**MOT test number** 137410869674**Result** ✓ Passed**Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

**MOT #14**

2015-11-20 11:33

**MOT test number**

691142902204

**Result****✗ Failed**

- Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front Brake hose excessively deteriorated (3.6.B.4d)
- Fail** Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Traction control light lamp on
- Fail** Offside Rear Seat belt damaged sufficient to obstruct correct operation of the belt (5.2.2a)
- Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front Anti-roll bar insecure (2.4.G.1)
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Fail** Offside Front Brake hose excessively deteriorated (3.6.B.4d)
- Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #13**

2014-10-24 11:00

**MOT test number**

195717894254

**Result**

✓ Passed

**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #12**

2014-10-13 12:59

**MOT test number**

918926484225

**Result**

✗ Failed

**Fail** Nearside Front Headlamp not working on main beam (1.7.5a)**Fail** Offside Front Lower Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Front Upper Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Main beam 'tell-tale' not working (1.7.4c)**Fail** Offside Front Headlamp not working on main beam (1.7.5a)**Fail** Nearside Front Lower Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #11**

2013-10-24 14:22

**MOT test number**

549757293263

**Result**

✓ Passed

**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #10**

2013-10-21 12:52

**MOT test number**

717394793275

**Result****✗ Failed****Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Upper Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Upper Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #9**

2012-09-20 16:47

**MOT test number**

377094562461

**Result****✓ Passed****Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #8** 2012-09-20 16:47**MOT test number** 697354762209**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Pass with rectification** Nearside Front Headlamp aim too far to the left (1.8)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2011-09-27 14:31**MOT test number** 755050171223**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Centre Exhaust has part of the system slightly deteriorated (7.1.1a)

**MOT #6** 2011-09-27 14:31**MOT test number** 458870571209**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Centre Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #5** 2010-09-22 17:09**MOT test number** 974655360290**Result** ✓ Passed**MOT #4** 2009-09-18 16:19**MOT test number** 150251769228**Result** ✓ Passed**MOT #3** 2009-09-18 16:19**MOT test number** 380331469412**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #2** 2008-09-18 16:54**MOT test number** 114042068211**Result** ✓ Passed



MOT #1	2007-09-21 16:58
MOT test number	881334067204
Result	✓ Passed
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
10 January 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	10 January 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>BN54YWM</b>
Plate since	2020-03-29
Current registration	 <b>BN54YWM</b>
Plate since	2020-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-09-23
Last registration	2024-01-10
Complete history	<a href="#">See info</a>



Registration #1	2004-09-23	19 mi
Registration #2	2007-09-21	78.803 mi
Registration #3	2008-09-18	101.578 mi
Registration #4	2009-09-18	117.982 mi
Registration #5	2010-09-22	134.229 mi
Registration #6	2011-09-27	143.353 mi
Registration #7	2012-09-20	145.652 mi
Registration #8	2013-10-21	164.161 mi
Registration #9	2013-10-24	164.295 mi
Registration #10	2014-10-13	184.154 mi
Registration #11	2014-10-24	184.154 mi
Registration #12	2015-05-20	201.277 mi
Registration #13	2015-05-20	201.277 mi
Registration #14	2015-05-20	201.277 mi
Registration #15	2015-05-20	201.277 mi
Registration #16	2015-05-20	201.277 mi
Registration #17	2015-05-20	201.277 mi
Registration #18	2015-05-20	201.277 mi
Registration #19	2015-05-20	201.277 mi
Registration #20	2015-05-20	201.277 mi
Registration #21	2015-05-20	201.277 mi
Registration #22	2015-05-20	201.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2175 mm
Height	1940 mm
Length	4707 mm
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	AXB 046048